



Site Safety and Compliance Guidelines for the inspection, removal and collection of the  
“Power Test 35X06 dyno testing facility” at R. Moore & Sons, Kewdale, WA.

Inspection

- Inspection by appointment only
- Site entry conditions:
  - Safety shoes (steel toe or equivalent)
  - Safety Glasses (Medium Impact)  
Note: Safety Glasses can be supplied to Visitors by RMS if required.
  - Report to main administration and complete Visitor/Contractor sign in process
  - Visitor High Visibility Vest will be supplied by RMS

Removal

- Details to be provided of Contractor/Sub-Contractor engaged to perform removal works:
  - Current certificate of insurance – Public Liability
  - Current certificate of insurance – Workers Compensation
  - Names of workers attending site
  - Copies of relevant licenses and certificates of competency e.g. Licence to Perform High Risk Work (relevant class), Construction Industry Safety Induction (White Card), Working Safely at Heights etc.
- Contractor/Sub-Contractor Workers performing works:
  - Cotton Drill Shirt (long or short sleeve)
  - Cotton Drill Pants
  - Safety Shoes (steel toe or equivalent)
  - Risk Assessment e.g. Job Safety/Hazard Analysis
  - Work from heights must be planned and completed in a safe manner e.g. Mobile Elevated Work Platform (MEWP), Scaffold, Platform Ladder etc.
  - Hot Works
    - a) No ignition sources within 3 meters of the Bulk Diesel Fuel Storage tanks.
    - b) If there is a need to perform Hot Works within 3 meters of the Bulk Diesel Fuel Storage Tanks e.g. Grinding or Oxy/Acet, additional controls are required e.g. Fire Watch.
    - c) Strictly no use of 7” or 9” angle grinders on site at all.
    - d) Adequate controls to be in place e.g. relevant PPE, fire blankets etc.
- Adequate task specific PPE to be worn by the Contractor/Sub-Contractor Workers e.g. Hearing Protection, High Impact Face Shields, Welding Jackets, Gloves etc.
- Tools/ Equipment used must be of a serviceable condition. All lifting equipment must have a current inspection tag attached, and all electrical equipment must have a current inspection and test tag attached.

Pick up

- Pick-up by appointment only
- Site entry conditions:
  - Safety shoes (steel toe or equivalent)
  - Safety Glasses (Medium Impact)  
Note: Safety Glasses can be supplied to Visitors by RMS if required.
  - Report to main administration and complete Visitor/Contractor sign in process
  - Visitor High Visibility Vest will be supplied by RMS
- Valid form of photo identification to be presented e.g. Drivers Licence.

**IMPORTANT NOTE:** All works will be monitored ensuring compliance to Work Health & Safety Legislation (Western Australia) and R. Moore & Sons requirements, as detailed above. Works found to be non-compliant will be stopped immediately.