

Work Order	Description	Start Date	Status	Cost Centre	Comp Code	PM Task	Branch	Finish Date	Done @	Schedule Week
AM628194	MD6250 BELT TENSIONER	17-Jan-25	F	80700401	1000	102808	EQ	17-Jan-25	4001	WODF_2025_03
AM655015	MD6250 COUPLING ELEMENT JOINTS - ENGINE TO PUMP DRIVE	11-Jun-25	F	80700401	1000	102719	EQ	12-Jun-25	5939	SHUT_2025_24
AM655016	MD6250 AIR COMPRESSOR COUPLING ELEMENT	11-Jun-25	F	80700401	1000	102759	EQ	12-Jun-25	5939	SHUT_2025_24
AM655018	MD6250 HOIST & PULL DOWN CABLES	11-Jun-25	F	80700401	3000	102676	EQ	12-Jun-25	5939	SHUT_2025_24
AM655022	MD6250 PUMP WATER INJECTION	11-Jun-25	F	80700401	7000	102689	EQ	14-Apr-25	5183	SHUT_2025_24
AM655023	MD6250 SEAT	11-Jun-25	F	80700401	8995	102699	EQ	12-Jun-25	5939	SHUT_2025_24
AM655024	MD6250 CHARGE PUMP	11-Jun-25	F	80700401	7000	102714	EQ	13-Jun-25	5939	SHUT_2025_24
AM752921	SHUT - MD6250 REPLACE COMPRESSOR OIL COOLER FRONT	13-Nov-25	F	80700401	7000	104310	EQ	11-Nov-25	7473	WODF_2025_46
AM752922	SHUT - MD6250 REPLACE COMPRESSOR OIL COOLER REAR LEFT	13-Nov-25	F	80700401	7000	104311	EQ	10-Nov-25	7473	WODF_2025_46
AM752923	SHUT - MD6250 REPLACE COMPRESSOR OIL COOLER REAR RIGHT	13-Nov-25	F	80700401	7000	104312	EQ	11-Nov-25	7473	WODF_2025_46
AM769337	MD6250 REPLACE CYLINDER LEFT MAST RAISE - PLAN ASAP	30-Oct-25	F	80700401	7000	102697	EQ	28-Oct-25	7472	WODF_2025_44
AM780637	MD6250 REPLACE ENGINE BELT TENSIONER	1-Sep-26	I	80700401	1000	102808	EQ			*
AM780638	MD6250 ENGINE MIDLIFE	1-Sep-26	I	80700401	1000	102671	EQ			*
AM780639	MD6250 REPLACE TURBOCHARGER LEFT	1-Sep-26	I	80700401	1000	102672	EQ			*
AM780640	MD6250 REPLACE TURBOCHARGER RIGHT	1-Sep-26	I	80700401	1000	102673	EQ			*
AM780641	MD6250 REPLACE IMPLEMENT PUMP LEFT, SEND OLD PUMP TO DC	1-Sep-26	I	80700401	7000	102677	EQ			*
AM780642	MD6250 REPLACE IMPLEMENT PUMP RIGHT, SEND OLD PUMP TO DC	1-Sep-26	I	80700401	7000	102678	EQ			*
AM780643	MD6250 REPLACE ROTATION MOTOR	1-Sep-26	I	80700401	7000	102679	EQ			*
AM780644	MD6250 REPLACE PISTON PUMP AUXILIARY	1-Sep-26	I	80700401	7000	102681	EQ			*
AM780645	MD6250 REPLACE HYDRAULIC ENGINE COOLER FAN MOTOR LEFT	1-Sep-26	I	80700401	7000	102683	EQ			*
AM780646	MD6250 REPLACE HYDRAULIC COOLER FAN MOTOR RIGHT	1-Sep-26	I	80700401	7000	102684	EQ			*
AM780647	MD6250 REPLACE HYDRAULIC FAN PUMP LEFT	1-Sep-26	I	80700401	7039	102685	EQ			*
AM780648	MD6250 REPLACE HYDRAULIC FAN PUMP RIGHT	1-Sep-26	I	80700401	7039	102686	EQ			*
AM780649	MD6250 REPLACE ROTARY HEAD GEARBOX	1-Sep-26	I	80700401	3000	102687	EQ			*
AM780650	MD6250 REPLACE CYLINDER JACK LEVEL REAR RIGHT	1-Sep-26	I	80700401	7000	102693	EQ			*
AM780651	MD6250 REPLACE CYLINDER JACK LEVEL REAR LEFT	1-Sep-26	I	80700401	7000	102694	EQ			*
AM780652	MD6250 REPLACE CYLINDER JACK LEVEL FRONT RIGHT	1-Sep-26	I	80700401	7000	102695	EQ			*
AM780653	MD6250 REPLACE CYLINDER JACK LEVEL FRONT LEFT	1-Sep-26	I	80700401	7000	102696	EQ			*
AM780654	MD6250 1 YEAR SERVICE AIR CONDITIONER MINOR	1-Sep-26	I	80700401	9500	104230	EQ			*
AM819495	MD6250 REPLACE CYLINDER PULL DOWN - PO # 2227225	2-Feb-26	F	80700401	7000	102690	EQ	3-Feb-26	7830	WODF_2026_06
AM895099	MD6250 REPLACE HOIST AND PULL DOWN CABLES	29-Jan-26	F	80700401	3000	102676	EQ	4-Feb-26	7832	
AM968653	MD6250 REPLACE COUPLING ENGINE TO PUMP DRIVE P/O 2392178	10-May-26	F	80700401	1000	102718	EQ	8-May-26	7833	