

DZ8210 DE MOBE PICTURES



Asset ID



LH Rear view showing Oil Leak from Banlaw fitting above LH Ripper Lift Cyl

LH Rear view showing weeping seals LH Ripper Tilt Cyl





LH Side View



Front View





LH Side Front View



LH Rear Side View



Rear View – Tilt and Lift Cyl seals weeping





Cab Pic 1





Cab Pic 2



Top Engine cover with Exhaust stacks removed





Blade Front View



Blade Rear View