

Asset ID	Plant Condition	Model	Strategy	major_minor	responsibility	PM Task Name	Frequency	Last Done	Component Hours	Life%	Work Order	Planned Date	UOM	SMU Date	SMU	Next Due	Due In (Hours)	Avg Utilisation	Forecast Date	Due In (Days)	Plant S/N	Criticality	Parts Cost	Task Type	Location
MG1027	IDLE	18M3	104539	MAJOR	LTP	18M3 ENGINE	14000	1/01/1900	9301	66.44%			HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	E9W00262		\$118,988.69	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104541	MAJOR	LTP	18M3 RADIATOR	14000	1/01/1900	9301	66.44%			HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	E9W00262		\$5,508.43	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104542	MAJOR	LTP	18M3 FAN	14000	1/01/1900	9301	66.44%			HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	E9W00262		\$3,998.98	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104543	MAJOR	LTP	18M3 HYDRAULIC OIL COOLER	14000	1/01/1900	9301	66.44%			HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	E9W00262		\$1,868.77	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104548	MAJOR	LTP	18M3 DRIVE SHAFT	14000	1/01/1900	9301	66.44%			HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	E9W00262		\$3,129.31	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104549	MAJOR	LTP	18M3 DIFFERENTIAL	14000	1/01/1900	9301	66.44%			HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	E9W00262		\$66,127.88	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104550	MAJOR	LTP	18M3 FINAL DRIVE LEFT	14000	1/01/1900	9301	66.44%			HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	E9W00262		\$6,793.88	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104551	MAJOR	LTP	18M3 FINAL DRIVE RIGHT	14000	1/01/1900	9301	66.44%			HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	E9W00262		\$6,793.88	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104553	MAJOR	LTP	18M3 TANDEM CHAIN RIGHT	14000	1/01/1900	9301	66.44%			HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	E9W00262		\$330.	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104556	MAJOR	LTP	18M3 WHEEL BEARING & BRAKE POS 3	14000	31/05/2024	9301	66.44%	AM438219	31/10/2025	HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	E9W00262		\$12,328.17	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104557	MAJOR	LTP	18M3 WHEEL BEARING & BRAKE POS 4	14000	31/05/2024	9301	66.44%	AM438211	31/10/2025	HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	E9W00262		\$12,328.17	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104558	MAJOR	LTP	18M3 WHEEL BEARING & BRAKE POS 5	14000	31/05/2024	9301	66.44%	AM438213	31/10/2025	HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	E9W00262		\$12,328.17	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104559	MAJOR	LTP	18M3 WHEEL BEARING & BRAKE POS 6	14000	31/05/2024	9301	66.44%	AM438214	31/10/2025	HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	E9W00262		\$12,328.17	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104560	MAJOR	LTP	18M3 STEERING VALVES	14000	1/01/1900	9301	66.44%			HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	E9W00262		\$4,025.43	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104563	MAJOR	LTP	18M3 STEERING / IMPLEMENT PISTON PUMP	14000	1/01/1900	9301	66.44%			HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	E9W00262		\$7,971.23	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104565	MAJOR	LTP	18M3 HYDRAULIC SYSTEM VALVE	14000	1/01/1900	9301	66.44%			HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	E9W00262		\$17,288.4	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104566	MAJOR	LTP	18M3 SWIVEL	14000	1/01/1900	9301	66.44%			HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	E9W00262		\$921.42	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104573	MAJOR	LTP	18M3 CIRCLE A FRAME	14000	1/01/1900	9301	66.44%			HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	E9W00262		\$45,036.51	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104579	MAJOR	LTP	18M3 CIRCLE DRIVE BOX	14000	1/01/1900	9301	66.44%			HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	E9W00262		\$31,336.3	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104583	MAJOR	LTP	18M3 FRONT AXLE ASSEMBLY	14000	1/01/1900	9301	66.44%			HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	E9W00262		\$59,030.61	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104552	MAJOR	LTP	18M3 TANDEM CHAIN LEFT	14000	8/07/2021	8674	61.96%			HOUR	3/04/2026	9301	14,627	5,326	0.15	21/06/2123	35,461	E9W00262		\$330.	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104546	MAJOR	LTP	18M3 TRANSMISSION	14000	5/06/2023	5232	37.37%			HOUR	3/04/2026	9301	18,069	8,768	0.15	17/04/2186	58,407	E9W00262		\$110,237.83	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104571	MAJOR	LTP	18M3 CIRCLE DRIVE MOTOR	14000	8/08/2023	4699	-33.56%			HOUR	3/04/2026	9301	28,000	18,699	0.15	25/07/2367	124,614	E9W00262		\$9,412.46	Component Changeout	GUILDFORD YARD

Asset ID	Plant Condition	Model	Strategy	major	minor	responsibility	PM Task Name	Frequency	Last Done	Component Hours	Life%	Work Order	Planned Date	UOM	SMU Date	SMU	Next Due	Due In (Hours)	Avg Utilisation	Forecast Date	Due In (Days)	Plant S/N	Criticality	Parts Cost	Task Type	Location
MG1027	IDLE	18M3	104584	MINOR	MEM		18M3 MINOR AIR CONDITIONER MAINTENANCE	7000	1/01/1900	5001	71.44%			HOUR	3/04/2026	9301	11,300	1,999	0.15	28/09/2062	13,281	ESW00262		\$0.	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104578	MINOR	MEM		18M3 RIPPER LIFT CYLINDER	14000	1/01/1900	9301	66.44%			HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	ESW00262		\$10,760.65	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104580	MINOR	MEM		18M3 ARTICULATION	14000	1/01/1900	9301	66.44%			HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	ESW00262		\$6,266.73	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	100786	MINOR	MEM		18M3 BLADE CUSHION ACCUMULATOR POS 1	14000	1/01/1900	7301	52.15%			HOUR	3/04/2026	9301	16,000	6,699	0.15	12/07/2148	44,614	ESW00262		\$4,183.64	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104564	MINOR	MEM		18M3 SECONDARY STEERING PUMP	14000	1/01/1900	7301	52.15%			HOUR	3/04/2026	9301	16,000	6,699	0.15	12/07/2148	44,614	ESW00262		\$4,037.42	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104567	MINOR	MEM		18M3 BLADE CUSHION ACCUMULATOR POS 1	14000	1/01/1900	7301	52.15%			HOUR	3/04/2026	9301	16,000	6,699	0.15	12/07/2148	44,614	ESW00262		\$4,183.64	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104725	MINOR	MEM		18M3 BRAKE ACCUMULATOR POS 1	14000	1/01/1900	7301	52.15%			HOUR	3/04/2026	9301	16,000	6,699	0.15	12/07/2148	44,614	ESW00262		\$4,183.64	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104755	MINOR	MEM		18M3 BRAKE ACCUMULATOR POS 2	14000	1/01/1900	7301	52.15%			HOUR	3/04/2026	9301	16,000	6,699	0.15	12/07/2148	44,614	ESW00262		\$4,183.64	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104582	MINOR	MEM		18M3 SEAT	6000	17/04/2023	3004	50.07%			HOUR	3/04/2026	9301	12,297	2,996	0.15	8/12/2080	19,927	ESW00262		\$11,886.64	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104572	MINOR	MEM		18M3 WHEEL LEAN CYLINDER	7000	8/08/2023	2536	36.23%			HOUR	3/04/2026	9301	13,765	4,464	0.15	26/09/2107	29,714	ESW00262		\$3,445.9	Condition Based Component	GUILDFORD YARD
MG1027	IDLE	18M3	107032	MINOR	MEM		18M3 TURBO AND FEED LINES	7000	1/01/1900	2536	36.23%			HOUR	3/04/2026	9301	13,765	4,464	0.15	26/09/2107	29,714	ESW00262		\$0.	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	107033	MINOR	MEM		18M3 THERMOSTAT	7000	1/01/1900	2536	36.23%			HOUR	3/04/2026	9301	13,765	4,464	0.15	26/09/2107	29,714	ESW00262		\$0.	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	107034	MINOR	MEM		18M3 FUEL TRANSFER PUMP	7000	1/01/1900	2536	36.23%			HOUR	3/04/2026	9301	13,765	4,464	0.15	26/09/2107	29,714	ESW00262		\$0.	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104585	MINOR	MEM		18M3 MAJOR AIR CONDITIONER MAINTENANCE	14000	1/01/1900	5001	35.72%			HOUR	3/04/2026	9301	18,300	8,999	0.15	5/07/2190	59,947	ESW00262		\$0.	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104547	MINOR	MEM		18M3 UNIVERSAL JOINTS	7000	8/08/2023	2301	32.87%			HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	ESW00262		\$666.42	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104554	MINOR	MEM		18M3 WHEEL BEARING POS 1	7000	1/11/2023	2301	32.87%			HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	ESW00262		\$1,093.75	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104555	MINOR	MEM		18M3 WHEEL BEARING POS 2	7000	1/11/2023	2301	32.87%			HOUR	3/04/2026	9301	14,000	4,699	0.15	10/01/2112	31,281	ESW00262		\$1,093.75	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104575	MINOR	MEM		18M3 BLADE SIDE SHIFT CYLINDER	14000	1/10/2024	4056	28.97%			HOUR	3/04/2026	9301	19,245	9,944	0.15	3/04/2171	66,247	ESW00262		\$8,097.31	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104544	MINOR	MEM		18M3 HYDRAULIC FAN MOTOR	7000	8/08/2023	301	4.30%			HOUR	3/04/2026	9301	16,000	6,699	0.15	12/07/2148	44,614	ESW00262		\$4,234.92	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104545	MINOR	MEM		18M3 FAN PUMP/BRAKE PUMP	7000	8/08/2023	301	4.30%			HOUR	3/04/2026	9301	16,000	6,699	0.15	12/07/2148	44,614	ESW00262		\$3,439.43	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104561	MINOR	MEM		18M3 STEERING CYLINDER LEFT	7000	8/08/2023	301	4.30%			HOUR	3/04/2026	9301	16,000	6,699	0.15	12/07/2148	44,614	ESW00262		\$3,904.84	Condition Based Component	GUILDFORD YARD
MG1027	IDLE	18M3	104562	MINOR	MEM		18M3 STEERING CYLINDER RIGHT	7000	8/08/2023	301	4.30%			HOUR	3/04/2026	9301	16,000	6,699	0.15	12/07/2148	44,614	ESW00262		\$3,904.84	Condition Based Component	GUILDFORD YARD
MG1027	IDLE	18M3	104570	MINOR	MEM		18M3 BLADE TILT CYLINDER	7000	8/08/2023	301	4.30%			HOUR	3/04/2026	9301	16,000	6,699	0.15	12/07/2148	44,614	ESW00262		\$7,824.82	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104577	MINOR	MEM		18M3 ARTICULATION CYLINDER RIGHT	7000	8/08/2023	301	4.30%			HOUR	3/04/2026	9301	16,000	6,699	0.15	12/07/2148	44,614	ESW00262		\$6,697.55	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104574	MINOR	MEM		18M3 CENTERSHIFT CYLINDER	14000	5/02/2026	1	0.01%			HOUR	3/04/2026	9301	23,300	13,999	0.15	10/10/2281	93,281	ESW00262		\$8,835.1	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104581	MINOR	MEM		18M3 BLADE	14000	30/09/2023	-699	-4.99%			HOUR	3/04/2026	9301	24,000	14,699	0.15	20/07/2294	97,947	ESW00262		\$52,000.	Condition Based Component	GUILDFORD YARD
MG1027	IDLE	18M3	104569	MINOR	MEM		18M3 LIFT/HOIST CYLINDER RIGHT	7000	1/10/2024	-944	-13.49%			HOUR	3/04/2026	9301	17,245	7,944	0.15	3/04/2171	52,914	ESW00262		\$11,007.46	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104576	MINOR	MEM		18M3 ARTICULATION CYLINDER LEFT	7000	1/10/2024	-944	-13.49%			HOUR	3/04/2026	9301	17,245	7,944	0.15	3/04/2171	52,914	ESW00262		\$6,697.55	Component Changeout	GUILDFORD YARD
MG1027	IDLE	18M3	104568	MINOR	MEM		18M3 LIFT/HOIST CYLINDER LEFT	7000	3/08/2025	-954	-13.63%			HOUR	3/04/2026	9301	17,255	7,954	0.15	9/06/2171	52,981	ESW00262		\$11,007.46	Component Changeout	GUILDFORD YARD

Work Order	Description	Start Date	Status	Cost Centre	Comp Code	PM Task	Branch	Finish Date	Done @	Schedule Week
AM861795	NDT STUB AXLE INSPECTIONS	25-Jan-26	F	80700401	IN8502	800015	EQ	13-Feb-26	9300	
AM813061	REPLACE BLADE TILT CYLINDER END CAPS,SHIMS,CUPS	13-Feb-26	F	80700401	7000		EQ	5-Feb-26	9300	
AM778821	LH LIFT CYLINDER EXTRA PARTS FOR FITMENT	13-Feb-26	F	80700401	7420-LH		EQ	5-Feb-26	9300	
AM744353	16M - 18M CENTERSHIFT CYLINDER	19-Oct-25	F	80700401	7440	104574	EQ	5-Feb-26	9300	
AM825136	CARE AND MAINTENANCE RUN UP	4-Nov-25	F	80700401	INSP	800830	EQ	8-Nov-25	9300	WODW_2025_45
AM822254	CARE AND MAINTENANCE RUN UP	20-Oct-25	F	80700401	INFNT	800830	EQ	22-Oct-25	9300	WODW_2025_43
AM802580	CARE AND MAINTENANCE RUN UP	18-Sep-25	F	80700401	INFNT	800830	EQ	22-Sep-25	9300	WODW_2025_38
AM801432	NDT STUB AXLE INSPECTIONS	20-Sep-25	F	80700401	IN8502	800015	EQ	19-Sep-25	9300	
AM794219	CARE AND MAINTENANCE RUN UP	11-Sep-25	F	80700401	INFNT	800830	EQ	11-Sep-25	9300	WODW_2025_37
AM788378	CARE AND MAINTENANCE RUN UP	3-Sep-25	F	80700401	INFNT	800830	EQ	7-Sep-25	9299	WODW_2025_36
AM784053	CARE AND MAINTENANCE RUN UP	30-Aug-25	F	80700401	INFNT	800830	EQ	1-Sep-25	9299	WODW_2025_35
AM770494	CARE AND MAINTENANCE RUN UP	17-Aug-25	F	80700401	INFNT	800830	EQ	17-Aug-25	9299	WODW_2025_33
AM777641	WESTRAC SOFTWARE UPDATE ON SERVICE	1-Aug-25	F	80700401	9000		EQ	14-Aug-25	9299	
AM782715	INSPECT AND REPAIR HYDRAULIC LEAK	9-Aug-25	F	80700401	7000		EQ	9-Aug-25	9299	
AM782260	LADDER HANGING OFF REAR LH SIDE	8-Aug-25	F	80700401	MISC		EQ	8-Aug-25	9285	
AM779235	AFFF LOW PRESSURE ALARM	4-Aug-25	F	80700401	MISC		EQ	4-Aug-25	9260	
AM778746	BLADE CUSHION FAULT	3-Aug-25	F	80700401	9000		EQ	3-Aug-25	9255	
AM755598	16M - 18M LIFT/HOIST CYLINDER LEFT	30-Jul-25	F	80700401	7420-LH	104568	EQ	3-Aug-25	9255	
AM778688	INSTALL NEW RADIO UPDATED	3-Aug-25	F	80700401	MISC		EQ	3-Aug-25	9255	
AM754644	CARE AND MAINTENANCE RUN UP	2-Aug-25	F	80700401	INSP	800830	EQ	2-Aug-25	9253	WODW_2025_31
AM765554	REPALCE FAULTY ARTICULATION CHECK VALVE	17-Aug-25	F	80700401	9000		EQ	1-Aug-25	9253	
AM613373	REPLACE PARK BRAKE PRESSURE SENSOR TAKEN FOR MG1032	10-Aug-25	F	80700401	9000		EQ	26-Jul-25	9253	
AM740690	FIT NEW HEADLIGHT ASSY & MOUNTING CLAMPS - REQ 1076093	9-Sep-25	F	80700401	9000		EQ	26-Jul-25	9253	
AM737020	CHANGE OUT LATCH TAKEN FOR MG1036	9-Sep-25	F	80700401	0021		EQ	26-Jul-25	9253	
AM737021	REPLACE HEAD LAMP TAKEN FOR MG1036	9-Sep-25	F	80700401	9000		EQ	26-Jul-25	9253	
AM754557	CARE AND MAINTENANCE RUN UP	23-Jul-25	F	80700401	INSP	800830	EQ	25-Jul-25	9253	WODW_2025_30
AM754436	CARE AND MAINTENANCE RUN UP	18-Jul-25	F	80700401	INFNT	800830	EQ	18-Jul-25	9253	WODW_2025_29
AM746519	CARE AND MAINTENANCE RUN UP	9-Jul-25	F	80700401	INFNT	800830	EQ	9-Jul-25	9253	WODW_2025_28
AM710350	CARE AND MAINTENANCE RUN UP	1-Jul-25	F	80700401	INFNT	800830	EQ	1-Jul-25	9253	WODW_2025_27
AM727797	NDT STUB AXLE INSPECTIONS	25-Jun-25	F	80700401	IN8502	800015	EQ	30-Jun-25	9253	WODW_2025_26
AM746431	CARE AND MAINTENANCE RUN UP	25-Jun-25	F	80700401	INFNT	800830	EQ	30-Jun-25	9253	WODW_2025_26
AM753306	REPLACE ARTIC JOINT CHECK VALVE	29-Jun-25	F	80700401	7000		EQ	29-Jun-25	9253	
AM706048	CARE AND MAINTENANCE RUN UP	17-Jun-25	F	80700401	INFNT	800830	EQ	20-Jun-25	9253	WODW_2025_25
AM701197	CARE AND MAINTENANCE RUN UP	11-Jun-25	F	80700401	INFNT	800830	EQ	11-Jun-25	9253	WODW_2025_24
AM727747	MOTOR GRADER 12 MONTH AFFF SERVICE	1-Jun-25	F	80700401	IN0707	800027	EQ	6-Jun-25	9253	WODW_2025_22
AM731689	CARE AND MAINTENANCE RUN UP	3-Jun-25	F	80700401	INFNT	800830	EQ	3-Jun-25	9252	WODW_2025_23
AM678231	CIRCLE WEAR PACK, BADLY WORN (WELD - BUILD UP)	1-Jun-25	F	80700401	8000		EQ	2-Jun-25	9252	WODW_2025_22
AM660552	REPLACE HYDRAULIC LEVEL GAUGE	1-Jun-25	F	80700401	0021		EQ	2-Jun-25	9252	WODW_2025_22
AM706573	REPLACE FAILED WASHER MOTORS	1-Jun-25	F	80700401	0021		EQ	2-Jun-25	9252	WODW_2025_22
AM695836	REPLACE ARTIC LOCK PIN	1-Jun-25	F	80700401	MISC		EQ	2-Jun-25	9252	WODW_2025_22
AM660560	REPLACE IMPLEMENT LOCK OUT SWITCH	1-Jun-25	F	80700401	0021		EQ	2-Jun-25	9252	WODW_2025_22
AM660550	REPLACE CENTERSHIFT INDICATOR AND SHIM	1-Jun-25	F	80700401	0021		EQ	2-Jun-25	9252	WODW_2025_22
AM682045	C/O GREASE PUMP VALVE & GREASE TANK BREATHER	1-Jun-25	F	80700401	0021		EQ	2-Jun-25	9252	WODW_2025_22
AM660553	RESEAL REMOTE ENGINE OIL FILTER HOSE.	1-Jun-25	F	80700401	0021		EQ	2-Jun-25	9252	WODW_2025_22
AM693141	CARE AND MAINTENANCE RUN UP	1-Jun-25	F	80700401	INFNT	800830	EQ	2-Jun-25	9252	WODW_2025_22
AM706576	REPLACE FAILED WORK LIGHTS - RH TOP REAR & 3 X TOP FRONT	1-Jun-25	F	80700401	9000		EQ	1-Jun-25	9252	WODW_2025_22
AM660555	REPLACE DAMAGED BLADE SIDESHIFT HOSES	1-Jun-25	F	80700401	7000		EQ	1-Jun-25	9252	WODW_2025_22
AM680344	CARE AND MAINTENANCE RUN UP	24-May-25	F	80700401	INFNT	800830	EQ	22-May-25	9252	WODW_2025_21
AM688138	CARE AND MAINTENANCE RUN UP	15-May-25	F	80700401	INFNT	800830	EQ	17-May-25	9252	WODW_2025_20
AM710230	CARE AND MAINTENANCE RUN UP	30-Apr-25	F	80700401	INFNT	800830	EQ	30-Apr-25	9252	WODW_2025_18
AM680219	CARE AND MAINTENANCE RUN UP	25-Apr-25	F	80700401	INFNT	800830	EQ	26-Apr-25	9252	WODW_2025_17
AM697083	CARE AND MAINTENANCE RUN UP	13-Apr-25	F	80700401	INFNT	800830	EQ	13-Apr-25	9252	WODW_2025_15
AM695835	REPLACE LHS DOOR GLASS	6-Apr-25	F	80700401	MISC		EQ	6-Apr-25	9253	WODW_2025_14
AM642307	CARE AND MAINTENANCE RUN UP	5-Apr-25	F	80700401	INFNT	800830	EQ	6-Apr-25	9253	WODW_2025_14
AM624886	CARE AND MAINTENANCE RUN UP	21-Mar-25	F	80700401	INFNT	800830	EQ	21-Mar-25	9252	WODW_2025_12
AM678294	REFIT SEAT - USED ON MG1030	19-Feb-25	F	80700401	8995		EQ	5-Mar-25	9252	
AM619348	CARE AND MAINTENANCE RUN UP	24-Feb-25	F	80700401	INFNT	800830	EQ	24-Feb-25	9252	WODW_2025_09
AM657724	NDT STUB AXLE INSPECTIONS	24-Feb-25	F	80700401	IN8502	800015	EQ	22-Feb-25	9252	WODW_2025_09
AM668610	DOOR ALARM FAULT	5-Feb-25	F	80700401	9000		EQ	21-Feb-25	9252	
AM662978	REPLACE WINDOW TAKEN FOR MG1032	4-Feb-25	F	80700401	0021		EQ	3-Feb-25	9248	
AM660467	REPLACE SEAT DAMPER TAKEN FOR MG1030	24-Jan-25	F	80700401	8995		EQ	28-Jan-25	9246	
AM601903	REPLACE BLADE SLIDE/TILT HOSES - U/S	31-Dec-24	F	80700401	7000		EQ	25-Jan-25	9246	
AM601678	REPLACE REMOTE ENGINE OIL FILTER HOSE	31-Dec-24	F	80700401	1000		EQ	25-Jan-25	9246	
AM601704	REPLACE O RINGS ON CAB ACCESS LADDER VALVE	31-Dec-24	F	80700401	0021		EQ	25-Jan-25	9246	
AM627127	INSPECT THE TURBO OIL LINES AND ATTACH	31-Dec-24	F	80700401	0021		EQ	24-Jan-25	9246	
AM591099	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	31-Dec-24	F	80700401	9000	899995	EQ	24-Jan-25	9246	
AM434082	WESTRAC DIAGNOSE/ REPAIR L/H BRAKE PACKS BYPASSING	31-Dec-24	F	80700401	3000		EQ	31-Dec-24	9246	
AM441742	REPLACE SEAT BELT - BUCKLE SWITCH U/S	31-Dec-24	F	80700401	8995		EQ	31-Dec-24	9246	
AM619266	CARE AND MAINTENANCE RUN UP	11-Dec-24	F	80700401	INSP	800830	EQ	11-Dec-24	9246	WODW_2024_50
AM601705	REMOVE AND REPLACE LHR BENT ACCESS STEP	27-Nov-24	F	80700401	0021		EQ	27-Nov-24	9246	WODW_2024_48
AM619244	CARE AND MAINTENANCE RUN UP	27-Nov-24	F	80700401	INFNT	800830	EQ	27-Nov-24	9246	
AM601703	REPLACE LH CAB DOOR SEAL - PERISHED	27-Nov-24	F	80700401	0021		EQ	27-Nov-24	9246	WODW_2024_48
AM563741	REPLACE LH CAB DOOR SEAL	27-Nov-24	F	80700401	8000		EQ	27-Nov-24	9246	WODW_2024_48
AM601670	REPLACE LH STEER CYLINDER PLUG FITTED TO CORRECT OEM PLUG	27-Nov-24	F	80700401	7000		EQ	27-Nov-24	9246	WODW_2024_48
AM563742	REPLACE ALL WINDOW WIPER BLADES ON CAB	27-Nov-24	F	80700401	MISC		EQ	27-Nov-24	9246	WODW_2024_48
AM583933	CARE AND MAINTENANCE RUN UP	20-Nov-24	F	80700401	INFNT	800830	EQ	20-Nov-24	9246	WODW_2024_47
AM570285	NDT STUB AXLE INSPECTIONS	10-Oct-24	F	80700401	IN8502	800015	EQ	2-Nov-24	9245	
AM570286	CARE AND MAINTENANCE RUN UP	28-Oct-24	F	80700401	INFNT	800830	EQ	30-Oct-24	9245	WODW_2024_44
AM567314	CARE AND MAINTENANCE RUN UP	23-Oct-24	F	80700401	INFNT	800830	EQ	23-Oct-24	9245	WODW_2024_43
AM592384	INVESTIGATE AFFF LOW PRESSURE WARNING	17-Oct-24	F	80700401	9000		EQ	17-Oct-24	9245	
AM560071	CARE AND MAINTENANCE RUN UP	16-Oct-24	F	80700401	INFNT	800830	EQ	16-Oct-24	9245	WODW_2024_42
AM559238	REPLACE STEERING CYLINDER DRAIN PLUGS REQ 872993	1-Oct-24	F	80700401	0021		EQ	3-Oct-24	9245	WODW_2024_40

Work Order	Description	Start Date	Status	Cost Centre	Comp Code	PM Task	Branch	Finish Date	Done @	Schedule Week
AM563733	FIRE SUPPRESSION LOW ON GAUGE - PWR TO INVESTIGATE	1-Oct-24	F	80700401	MISC		EQ	2-Oct-24	9245	WODW_2024_40
AM480024	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	30-Sep-24	F	80700401	9000	899995	EQ	2-Oct-24	9245	WODW_2024_40
AM518427	REPLACE MISSING LH DOOR(ENCLOSURE)	1-Oct-24	F	80700401	9000		EQ	2-Oct-24	9245	WODW_2024_40
AM518432	REPLACE WORN BLADE SLIDES	1-Oct-24	F	80700401	0050		EQ	1-Oct-24	9245	WODW_2024_40
AM437912	16M - 18M ARTICULATION CYLINDER LEFT	30-Sep-24	F	80700401	7414-LH	104576	EQ	1-Oct-24	9245	WODW_2024_40
AM437909	16M - 18M LIFT/HOIST CYLINDER LEFT	1-Oct-24	F	80700401	7420-LH	104568	EQ	1-Oct-24	9245	WODW_2024_40
AM437911	16M - 18M BLADE SIDE SHIFT CYLINDER	30-Sep-24	F	80700401	7540	104575	EQ	1-Oct-24	9245	WODW_2024_40
AM437910	16M - 18M LIFT/HOIST CYLINDER RIGHT	30-Sep-24	F	80700401	7420-RH	104569	EQ	1-Oct-24	9245	WODW_2024_40
AM556455	CARE AND MAINTENANCE RUN UP	18-Sep-24	F	80700401	INFNT	800830	EQ	18-Sep-24	9245	WODW_2024_38
AM543926	CARE AND MAINTENANCE RUN UP	10-Sep-24	F	80700401	INFNT	800830	EQ	11-Sep-24	9245	WODW_2024_37
AM522988	CARE AND MAINTENANCE RUN UP	7-Sep-24	F	80700401	INFNT	800830	EQ	8-Sep-24	9244	WODW_2024_36
AM519371	REPLACE MISSING RH DOOR	30-Sep-24	F	80700401	9000		EQ	2-Sep-24	9244	
AM541923	18M INSPECT BRAKE ACCUMULATOR POS 1	18-Sep-24	F	80700401	7646	700262	EQ	22-Aug-24	9244	
AM541914	18M INSPECT BLADE CUSHION ACCUMULATOR POS 2	18-Sep-24	F	80700401	7646	700251	EQ	22-Aug-24	9244	
AM516199	CARE AND MAINTENANCE RUN UP	22-Aug-24	F	80700401	INFNT	800830	EQ	22-Aug-24	9244	WODW_2024_34
AM541922	18M INSPECT BRAKE ACCUMULATOR POS 2	18-Sep-24	F	80700401	7646	700263	EQ	22-Aug-24	9244	
AM541915	18M INSPECT BLADE CUSHION ACCUMULATOR POS 1	18-Sep-24	F	80700401	7646	700250	EQ	22-Aug-24	9244	
AM509245	CARE AND MAINTENANCE RUN UP	12-Aug-24	F	80700401	INFNT	800830	EQ	12-Aug-24	9244	WODW_2024_33
AM335934	REAR CAMERA MOUNT, WELD BROKEN & METAL CRACKED	29-Jul-24	F	80700401	0021		EQ	5-Aug-24	9244	WODW_2024_31
AM509011	CARE AND MAINTENANCE RUN UP	29-Jul-24	F	80700401	INFNT	800830	EQ	31-Jul-24	9243	WODW_2024_31
AM379240	INSPECT AND REPAIR CENTRAL BLADE LOCK SYSTEM - BLADE	29-Jul-24	F	80700401	9000		EQ	31-Jul-24	9243	WODW_2024_31
AM398247	CTR SHIFT PIN WARMING LIGHT STAYS ON	29-Jul-24	F	80700401	9000		EQ	31-Jul-24	9243	WODW_2024_31
AM502495	CARE AND MAINTENANCE RUN UP	27-Jul-24	F	80700401	INFNT	800830	EQ	27-Jul-24	9243	WODW_2024_30
AM515989	18M INSPECT BRAKE ACCUMULATOR POS 1	15-Jul-24	F	80700401	0021	700262	EQ	26-Jul-24	9243	
AM515990	18M INSPECT BRAKE ACCUMULATOR POS 2	15-Jul-24	F	80700401	0021	700263	EQ	26-Jul-24	9243	
AM493894	CARE AND MAINTENANCE RUN UP	20-Jul-24	F	80700401	INFNT	800830	EQ	20-Jul-24	9243	WODW_2024_29
AM480445	CARE AND MAINTENANCE RUN UP	14-Jul-24	F	80700401	INFNT	800830	EQ	14-Jul-24	9242	WODW_2024_28
AM468160	NDT STUB AXLE INSPECTIONS	10-Jul-24	F	80700401	IN8502	800015	EQ	10-Jul-24	9242	
AM480348	CARE AND MAINTENANCE RUN UP	3-Jul-24	F	80700401	INFNT	800830	EQ	3-Jul-24	9242	WODW_2024_27
AM448044	CARE AND MAINTENANCE RUN UP	26-Jun-24	F	80700401	INFNT	800830	EQ	25-Jun-24	9242	WODW_2024_26
AM444285	CARE AND MAINTENANCE RUN UP	19-Jun-24	F	80700401	INFNT	800830	EQ	21-Jun-24	9241	WODW_2024_25
AM444257	CARE AND MAINTENANCE RUN UP	14-Jun-24	F	80700401	INFNT	800830	EQ	14-Jun-24	9241	WODW_2024_24
AM442371	CARE AND MAINTENANCE RUN UP	6-Jun-24	F	80700401	INFNT	800830	EQ	9-Jun-24	9240	WODW_2024_23
AM461719	FIRE SUPPRESSION ELECTRICAL FAULT SHUT DOWN	8-Jun-24	F	80700401	MISC		EQ	8-Jun-24	9240	
AM446641	FIT PLATE TO LH REAR WHEEL SPINDLE (MISSING)	16-Jun-24	F	80700401	0021		EQ	2-Jun-24	9240	
AM442354	CARE AND MAINTENANCE RUN UP	30-May-24	F	80700401	INFNT	800830	EQ	30-May-24	9240	WODW_2024_22
AM442333	CARE AND MAINTENANCE RUN UP	23-May-24	F	80700401	INFNT	800830	EQ	24-May-24	9240	WODW_2024_21
AM432586	REPLACE FRONT LIGHTS	23-May-24	F	80700401	9000		EQ	24-May-24	9240	WODW_2024_21
AM426144	C/O 30A FUSE IN LOCATION F8 TO CORRECT CIRCUIT BREAKER FUSE	23-May-24	F	80700401	9000		EQ	24-May-24	9240	WODW_2024_21
AM440354	C LAB - Flush and replace oil in both front wheels.	23-May-24	F	80700401	5000		EQ	24-May-24	9240	WODW_2024_21
AM435289	REPLACE BROKEN MIRROR	23-May-24	F	80700401	MISC		EQ	24-May-24	9240	WODW_2024_21
AM390754	CHANGE OUT ALL HOSE IN ARCTIC AREA	23-May-24	F	80700401	7000		EQ	23-May-24	9240	WODW_2024_21
AM414270	NDT STUB AXLE INSPECTIONS	16-Apr-24	F	80700401	IN8502	800015	EQ	1-May-24	9239	
AM433948	INVESTIGATE AND REPAIR OIL LEAK	24-Apr-24	F	80700401	7000		EQ	25-Apr-24	9238	
AM432468	LOOSE BOLTS IN HAND RAILS	22-Apr-24	F	80700401	0021		EQ	22-Apr-24		
AM414188	18M INSPECT RIDE CONTROL ACCUMULATOR POS 2	22-Apr-24	F	80700401	7646	700251	EQ	22-Apr-24	9199	
AM395332	MOTOR GRADER 12 MONTH AFF SERVICE	21-Apr-24	F	80700401	IN0707	800027	EQ	21-Apr-24	9199	WODG_2024_16
AM414251	CAT 16M - 18M GRADER 1000 HR PM SERVICE	21-Apr-24	F	80700401	P1000	900797	EQ	21-Apr-24	9199	WODG_2024_16
AM414187	18M INSPECT RIDE CONTROL ACCUMULATOR POS 1	21-Apr-24	F	80700401	7646	700250	EQ	21-Apr-24	9199	
AM431195	C/O CUTTING EDGES	19-Apr-24	F	80700401	GET		EQ	19-Apr-24	9177	
AM431196	FILL HYD OIL, DRAIN LH TANDEM	19-Apr-24	F	80700401	7000		EQ	19-Apr-24	9177	
AM426145	C/O LEAKING RH ARTICULATION	7-May-24	F	80700401	7000		EQ	17-Apr-24	9139	
AM429672	A/C NOT WORKING	15-Apr-24	F	80700401	9000		EQ	15-Apr-24	9154	
AM428247	IMPLEMENT LOCK OUT- CLEAN SWITCH	14-Apr-24	F	80700401	9000		EQ	14-Apr-24	9139	
AM423275	REPAIR AIR CON FAULT	4-Apr-24	F	80700401	9500		EQ	5-Apr-24	9024	
AM423614	AIR CONDITIONER NOT WORKING	5-Apr-24	F	80700401	9000		EQ	5-Apr-24		
AM423272	TOP UP HYDRAULIC OIL DRAIN LHS TANDEM AND RESET LEVEL	4-Apr-24	F	80700401	7000		EQ	4-Apr-24	9024	
AM422466	LADDER FUNCTION FAULT	2-Apr-24	F	80700401	9000		EQ	2-Apr-24		
AM419786	FIRE SUPPRESSION LOW.	30-Mar-24	F	80700401	MISC		EQ	30-Mar-24	8959	
AM419458	TANDEM/BRAKE BYPASS LEAKING HYDRAULIC OIL	29-Mar-24	F	80700401	7000		EQ	29-Mar-24	8945	
AM416154	REPLACED O RING ON SWIVEL JOINT	24-Mar-24	F	80700401	7000		EQ	24-Mar-24		
AM413953	REPLACE WORN OUT G.E.T	19-Mar-24	F	80700401	GET		EQ	20-Mar-24	8885	
AM402454	MAXMINE TO CARRY OUT INSTALLATION OF DATA SYSTEM	18-Mar-24	F	80700401	MISC		EQ	18-Mar-24	8860	
AM408573	CHANGE OUT 4X DRIVE TYRES	15-Mar-24	F	80700401	TYRE		EQ	15-Mar-24	8858	WODH_2024_11
AM411377	LOOSE GET BOLTS	14-Mar-24	F	80700401	0050		EQ	14-Mar-24	8858	
AM381921	CAT 16M - 18M GRADER 500 HR PM SERVICE	7-Mar-24	F	80700401	P0500	900796	EQ	8-Mar-24	8738	WODH_2024_10
AM384936	REPLACE RIPPER CYLINDER HOSES	7-Mar-24	F	80700401	1000		EQ	7-Mar-24	8738	WODH_2024_10
AM338651	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	7-Mar-24	F	80700401	9000	899995	EQ	7-Mar-24	8738	WODH_2024_10
AM384934	REPLACE TRANSMISSION BELLY GUARDS	7-Mar-24	F	80700401	1000		EQ	7-Mar-24	8738	WODH_2024_10
AM396816	REPLACE DRYER AS IT WAS OPEN TO AIR	7-Mar-24	F	80700401	9500		EQ	7-Mar-24	8738	WODH_2024_10
AM365380	REPLACE BLADE LIFT CYLINDER INSERTS/SHIMS	7-Mar-24	F	80700401	0050		EQ	7-Mar-24	8738	WODH_2024_10
AM312114	REPLACE 30A FUSE IN AIRCON CIRCUIT - F8 FUSE PANEL	7-Mar-24	F	80700401	9000		EQ	7-Mar-24	8738	WODH_2024_10
AM365379	REPLACE BLADE SLIDES	7-Mar-24	F	80700401	0050		EQ	7-Mar-24	8738	WODH_2024_10
AM373364	C LAB - Replace oil in both tandems. Check Magplugs.	17-Jan-24	F	80700401	5000		EQ	7-Mar-24	8738	
AM364691	REMOVE DAMAGED DRAIN PLUGS ON TANDEM AND REPLACE WITH NEW	7-Mar-24	F	80700401	3000		EQ	7-Mar-24	8738	WODH_2024_10
AM350628	REPLACE SEAT DAMPENER STRUT	7-Mar-24	F	80700401	0021		EQ	7-Mar-24	8738	WODH_2024_10
AM406938	REPLACE WORN CUTTING EDGES	6-Mar-24	F	80700401	GET		EQ	6-Mar-24	8728	
AM384935	REPLACE LEAKING ENGINE OIL FILTER HOSES	7-Mar-24	F	80700401	1000		EQ	1-Mar-24	8655	WODH_2024_10
AM400911	LOW GREASE ALARM	24-Feb-24	F	80700401	0091		EQ	24-Feb-24	8585	
AM399719	HYDRAULICS NOT ENGAGING	20-Feb-24	F	80700401	9000		EQ	20-Feb-24	8560	
AM399687	REPLACE BLADE CIRCLE WEAR PADS	20-Feb-24	F	80700401	0050		EQ	20-Feb-24	8560	
AM387122	EXCESSIVE MOVEMENT/DAMAGE TO BOTTOM ARTIC PIN AND BUSH	26-Jan-24	F	80700401	0021		EQ	19-Feb-24	8544	

Work Order	Description	Start Date	Status	Cost Centre	Comp Code	PM Task	Branch	Finish Date	Done @	Schedule Week
AM357985	REPLACE PWR BOTTLES	5-Jan-24	F	80700401	IN0707		EQ	17-Feb-24	8544	
AM335936	REPLACE MISSING DOOR PANEL	17-Nov-23	F	80700401	0021		EQ	16-Feb-24	8544	WODH_2023_46
AM383721	ACCIDENT DAMAGE	21-Jan-24	F	80700401	8000		EQ	22-Jan-24	8526	
AM336582	REPLACE ALL DRAW BAR CYLINDER END INSERTS & SHIMS	8-Nov-23	F	80700401	0021		EQ	22-Jan-24	8526	
AM383586	FIRE SUPPRESSION LOW ON GAS	21-Jan-24	F	80700401	9000		EQ	21-Jan-24	8519	
AM382733	REPLACE MISSING BLADE SLIDES	18-Jan-24	F	80700401	0050		EQ	19-Jan-24	8484	
AM382046	INVESTERGATE LOW TRANSMISSION PRESSURE FAULT ALARM	16-Jan-24	F	80700401	2000		EQ	17-Jan-24	8472	
AM382142	FIRE SUPPRESSION LOW	17-Jan-24	F	80700401	8000		EQ	17-Jan-24	8473	
AM379515	REPLACE DAMAGED TRANSMISSION DRAIN LINE FITTING	15-Jan-24	F	80700401	2000		EQ	15-Jan-24	8467	
AM382467	NDT STUB AXLE INSPECTIONS	10-Aug-23	F	80700401	IN8502	800015	EQ	15-Jan-24	8450	
AM378891	A FRAME CENTRE LOCK LIGHT STAYING ON	15-Jan-24	F	80700401	9000		EQ	15-Jan-24	8430	
AM378763	MACHINE WOULD NOT START	14-Jan-24	F	80700401	9000		EQ	14-Jan-24	8424	
AM378785	REPLACE FAILING BATTERY	14-Jan-24	F	80700401	9000		EQ	14-Jan-24	8424	
AM377465	MACHINE SHUTDOWN AND DASH HAS NO POWER	11-Jan-24	F	80700401	9000		EQ	11-Jan-24	8368	
AM344131	NDT STUB AXLE INSPECTIONS	31-Dec-23	F	80700401	IN8502	800015	EQ	10-Jan-24	8365	
AM369938	A/C BLOWING HOT AIR , INVESTERGATE AND REPAIR	6-Jan-24	F	80700401	9500		EQ	5-Jan-24	8313	
AM367813	INVESTIGATE TWO WAY FAULT	1-Jan-24	F	80700401	9000		EQ	1-Jan-24	8281	
AM366986	INVESTIGATE LOW FIRE SUPPRESSION PRESSURE	29-Dec-23	F	80700401	MISC		EQ	29-Dec-23	8240	
AM344153	CAT 16M - 18M GRADER 2000 HR PM SERVICE	19-Dec-23	F	80700401	P2000	900798	EQ	20-Dec-23	8229	WODH_2023_51
AM348503	PRESTART # HVAA136838 RHS LADDER LIGHT FLICKERING	20-Dec-23	F	80700401	INPRE	200000	EQ	20-Dec-23	8229	WODH_2023_51
AM362126	REPLACE G.E.T	18-Dec-23	F	80700401	GET		EQ	18-Dec-23	8220	
AM361525	REPLACE G.E.T	16-Dec-23	F	80700401	GET		EQ	16-Dec-23	8181	
AM360680	OIL LEAK LOSE HOSE	13-Dec-23	F	80700401	0021		EQ	14-Dec-23	8119	
AM358020	LOOSE BOLTS ON CIRCLE DRIVE	25-Jan-24	F	80700401	3300		EQ	8-Dec-23	8077	
AM350953	C LAB - Flush & Replace oil in both front wheels.	6-Dec-23	F	80700401	5000		EQ	7-Dec-23	8064	
AM350951	C LAB - Flush & replace Swing drive oil.	6-Dec-23	F	80700401	3300		EQ	7-Dec-23	8064	
AM350954	C LAB - Flush & Replace oil in RH Tandem.	6-Dec-23	F	80700401	5000		EQ	7-Dec-23	8064	
AM294866	REPLACE FIRE SUPPRESSION BOTTLES - DAMAGED AT WESTRAC	31-Jul-23	F	80700401	0021		EQ	7-Dec-23	8052	
AM357584	DIAGNOSE GREASE ALARM / GREASE LEAK AT TANK	6-Dec-23	F	80700401	0091		EQ	6-Dec-23	8045	
AM356986	DOOR ALARM FAULT - DIAGNOSE AND REPORT / REPAIR	5-Dec-23	F	80700401	9000		EQ	5-Dec-23	8045	
AM350630	REPLACE A/C COMPRESSOR AND RECEIVER DRIER	30-Nov-23	F	80700401	1000		EQ	1-Dec-23	7990	
AM351731	A/C FAULT	30-Nov-23	F	80700401	9500		EQ	1-Dec-23	7990	
AM342098	REPLACE FRONT TYRES	29-Nov-23	F	80700401	TYRE		EQ	30-Nov-23	7980	WODH_2023_48
AM349559	CHANGE OUT G.E.T	26-Nov-23	F	80700401	GET		EQ	26-Nov-23	7922	
AM348500	INVESTERGATE A/C NOT WORKING	23-Nov-23	F	80700401	9500		EQ	24-Nov-23	7922	
AM333671	REPLACE FLASHER MODULE - INTERMITTENT FAULT ON HAZARD LIGHT	17-Nov-23	F	80700401	9000		EQ	17-Nov-23	7866	WODH_2023_46
AM335942	REPLACE BLADE SLIDES	17-Nov-23	F	80700401	0021		EQ	16-Nov-23	7852	WODH_2023_46
AM345935	HYD OIL BYPASSING TO THE TANDEM	16-Nov-23	F	80700401	7000		EQ	16-Nov-23	7840	
AM344919	REPLACE BOTTOM RH BLADE SLIDE	15-Nov-23	F	80700401	0021		EQ	15-Nov-23	7839	
AM339614	ELECTRICAL FAULT - LIGHTS TURNING OFF	10-Nov-23	F	80700401	9000		EQ	10-Nov-23	7793	
AM339586	HAZARD LIGHT FAULT	9-Nov-23	F	80700401	9000		EQ	9-Nov-23	7789	
AM337567	INVESTIGATE AND REPAIR ELECTRICAL FAULT WITH HAZARD LIGHTS	5-Nov-23	F	80700401	9000		EQ	5-Nov-23	7777	
AM336576	REPAIR CRACK AROUND A FRAME BALL DAMAGE	1-Nov-23	F	80700401	8040		EQ	2-Nov-23	7750	
AM325239	16M - 18M WHEEL BEARING POS 1	9-Nov-23	F	80700401	5020-01	104554	EQ	1-Nov-23	7740	
AM325240	16M - 18M WHEEL BEARING POS 2	9-Nov-23	F	80700401	5020-02	104555	EQ	1-Nov-23	7740	
AM335842	CHANGE OUT BLADE G.E.T	30-Oct-23	F	80700401	0050		EQ	30-Oct-23	7740	
AM299881	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	29-Oct-23	F	80700401	9000	899995	EQ	30-Oct-23	7740	WODH_2023_43
AM316465	CAT 16M - 18M GRADER 500 HR PM SERVICE	29-Oct-23	F	80700401	P0500	900796	EQ	30-Oct-23	7740	WODH_2023_43
AM312318	INVESTIGATE CAUSE OF OIL BYPASSING INTO LHS TANDEM	29-Oct-23	F	80700401	0021		EQ	29-Oct-23	7740	WODH_2023_43
AM325795	PRESTART # AA136987 - LEFT ARTIC NOT WORKING	29-Oct-23	F	80700401	INPRE	200000	EQ	29-Oct-23	7740	WODH_2023_43
AM324189	DIAGNOSE AND REPAIR HIGH FERROUS METAL CONTENT IN LH HUB OIL	29-Oct-23	F	80700401	5020-01		EQ	29-Oct-23	7740	WODH_2023_43
AM326117	PRESTART # GREASE LINE POS 2 AIRCON STRUGGLES DURING THE DAY	29-Oct-23	F	80700401	INPRE	200000	EQ	29-Oct-23	7740	WODH_2023_43
AM335270	TRAMMING FAULT REQUIRES CALIBRATION	28-Oct-23	F	80700401	7580		EQ	28-Oct-23	7740	
AM334577	SNAPPED ALTERNATOR BELT	27-Oct-23	F	80700401	1000		EQ	27-Oct-23	7730	
AM333673	CHANGE OUT CUTTING EDGES	25-Oct-23	F	80700401	GET		EQ	25-Oct-23	7687	
AM328276	INVESTIGATE HAZARD LIGHTS IN/OP	19-Oct-23	F	80700401	9000		EQ	19-Oct-23	7636	
AM324107	X LAB - FLUSH AND REPLACE BOTH FRONT WHEEL HUB OILS.	18-Oct-23	F	80700401	5000		EQ	18-Oct-23	7624	WODH_2023_42
AM309775	NDT STUB AXLE INSPECTIONS	31-Oct-23	F	80700401	IN8502	800015	EQ	18-Oct-23	7612	
AM305446	REPLACE HYDRAULIC HOSE FROM MANIFOLD ON PUMP TO THE	18-Oct-23	F	80700401	7000		EQ	18-Oct-23	7624	WODH_2023_42
AM300961	RELOCATE THE 2 WAY RADIO ON THE CAB	18-Oct-23	F	80700401	0021		EQ	18-Oct-23	7624	WODH_2023_42
AM320677	CHANGE OUT ALL TYRES	9-Oct-23	F	80700401	TYRE		EQ	13-Oct-23	7549	
AM324714	REPLACE WORN GET	10-Oct-23	F	80700401	GET		EQ	11-Oct-23	7535	
AM325048	ELECTRICAL FAULTS ON MACHINE INVESTAGATE CAUSE AND REPAIR	31-Oct-23	F	80700401	9000		EQ	11-Oct-23	7535	
AM274962	REPLACE BLADE BRACKET	7-Oct-23	F	80700401	0050		EQ	9-Oct-23	7525	WODH_2023_40
AM304472	REPLACE DAMAGED ENGINE BAY DOOR	7-Oct-23	F	80700401	0021		EQ	8-Oct-23	7525	WODH_2023_40
AM318693	X LAB* - Repalce engine oil and filters.	7-Oct-23	F	80700401	1000		EQ	8-Oct-23	7525	WODH_2023_40
AM296527	REPLACE ARMREST R/H	7-Oct-23	F	80700401	1000		EQ	8-Oct-23	7525	WODH_2023_40
AM322759	TRANSMISSION HOSE DAMAGED	6-Oct-23	F	80700401	0021		EQ	6-Oct-23	7508	
AM321321	REMOVE AND WELD UP CRACK ON FITTING	3-Oct-23	F	80700401	7440		EQ	3-Oct-23	7432	
AM320890	REPAIR BROKEN WELD ON HANDRAIL	1-Oct-23	F	80700401	0021		EQ	2-Oct-23	7425	
AM295365	INSPECT GREASE COUPLINGS FOR SERVICEABILITY	3-Aug-23	F	80700401	0091		EQ	1-Oct-23	7425	
AM320660	REPAIR DANAGED STEP AND WINCH GUARD	1-Oct-23	F	80700401	0021		EQ	1-Oct-23	7425	
AM129526	16M - 18M BLADE - CHANGEOUT ONLY	2-Aug-22	F	80700401	0050	104581	EQ	30-Sep-23	7425	
AM318731	A/C NOT WORKING	27-Sep-23	F	80700401	9500		EQ	28-Sep-23	7399	
AM318658	X LAB - FLUSH AND REPLACE BOTH FRONT WHEEL HUB OILS.	27-Sep-23	F	80700401	5000		EQ	27-Sep-23	7399	
AM316873	INVESTIGATE POSSIBLE HYDRAULIC OIL LEAK	20-Sep-23	F	80700401	7000		EQ	20-Sep-23	7300	
AM316155	CHANGE OUT BLADE G.E.T	18-Sep-23	F	80700401	GET		EQ	18-Sep-23	7280	
AM274267	CAT 16M - 18M GRADER 1000 HR PM SERVICE	21-Jul-23	F	80700401	P1000	900797	EQ	16-Sep-23	7245	
AM314277	REPAIR TO THE LADDER, MISSING PIN.	14-Sep-23	F	80700401	0050		EQ	14-Sep-23	7229	
AM312327	REPLACE BLADE SLIDES	9-Sep-23	F	80700401	0021		EQ	10-Sep-23	7111	
AM312122	STEERING FAULT	9-Sep-23	F	80700401	9000		EQ	9-Sep-23	7111	
AM312028	ADJUST LADDER PROXY SWITCH	8-Sep-23	F	80700401	9000		EQ	8-Sep-23	7111	

Work Order	Description	Start Date	Status	Cost Centre	Comp Code	PM Task	Branch	Finish Date	Done @	Schedule Week
AM296898	MOTOR GRADER 6 MONTH AFFV SERVICE	7-Sep-23	F	80700401	IN0706	800026	EQ	4-Sep-23	7064	WODH_2023_36
AM308639	DIAGNOSIS A/C FAULT	4-Sep-23	F	80700401	9000		EQ	4-Sep-23	7064	
AM307115	DIGANOSIS OVER HEATING ISSUE	30-Aug-23	F	80700401	7000		EQ	30-Aug-23	6982	
AM305819	INVESTIGATE AND REPAIR HYDRAULIC LEAK REAR OF HYDRAULIC	27-Aug-23	F	80700401	7000		EQ	26-Aug-23	6971	
AM305364	INVESTIGTAE HYDRAULIC LEAK	24-Aug-23	F	80700401	7000		EQ	24-Aug-23	6938	
AM304776	REPLACE CUTTING EDGES	24-Aug-23	F	80700401	GET		EQ	24-Aug-23	6925	
AM302985	INTERMITTENT CHARGING FAULT	16-Sep-23	F	80700401	1000		EQ	21-Aug-23	6883	
AM302927	REPAIR PIVOT PINS ON STAIRS COME ADRIFT	19-Aug-23	F	80700401	8000		EQ	19-Aug-23	6883	
AM302814	DIAGNOSIS GREASE FAULT	19-Aug-23	F	80700401	0091		EQ	19-Aug-23	6883	
AM098518	16M - 18M FAN PUMP/BRAKE PUMP	1-Jul-23	F	80700401	7029	104545	EQ	8-Aug-23	6765	
AM129528	16M - 18M CIRCLE DRIVE MOTOR	2-Aug-22	F	80700401	7230	104571	EQ	8-Aug-23	6765	
AM098519	16M - 18M UNIVERSAL JOINTS	1-Jul-23	F	80700401	3038	104547	EQ	8-Aug-23	6765	
AM098516	16M - 18M ENGINE MIDLIFE	1-Jul-23	F	80700401	1004	104540	EQ	8-Aug-23	6765	
AM098517	16M - 18M HYDRAULIC FAN MOTOR	1-Jul-23	F	80700401	7232	104544	EQ	8-Aug-23	6765	
AM098526	16M - 18M ARTICULATION CYLINDER RIGHT	1-Jul-23	F	80700401	7414-RH	104577	EQ	8-Aug-23	6765	
AM098525	16M - 18M WHEEL LEAN CYLINDER	1-Jul-23	F	80700401	7580	104572	EQ	8-Aug-23	6765	
AM098524	16M - 18M BLADE TILT CYLINDER	1-Jul-23	F	80700401	7422	104570	EQ	8-Aug-23	6765	
AM098521	16M - 18M STEERING CYLINDER RIGHT	1-Jul-23	F	80700401	7542-RH	104562	EQ	8-Aug-23	6765	
AM098520	16M - 18M STEERING CYLINDER LEFT	1-Jul-23	F	80700401	7542-LH	104561	EQ	8-Aug-23	6765	
AM295707	CAT CONTRACTOR CONDUCTING TRANSMISSION FLASH UPGRADE	3-Aug-23	F	80700401	9000		EQ	4-Aug-23	16601	
AM269152	NDT STUB AXLE INSPECTIONS	17-Jul-23	F	80700401	IN8502	800015	EQ	31-Jul-23	6732	
AM287873	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	4-Jul-23	F	80700401	9000	899995	EQ	7-Jul-23	6732	
AM244348	CAT 16M - 18M GRADER 500 HR PM SERVICE	4-Jun-23	F	80700401	P0500	900796	EQ	5-Jun-23	6732	WODH_2023_22
AM266981	16M - 18M TRANSMISSION - PREMATURE FAILURE	4-Jul-23	F	80700401	2000	104546	EQ	5-Jun-23	6732	
AM236683	REPLACE MISSING LH REAR DOOR	4-Jun-23	F	80700401	0021		EQ	4-Jun-23	6732	WODH_2023_22
AM249995	REPLACE DAMAGED DOOR GLASS	4-Jun-23	F	80700401	0021		EQ	4-Jun-23	6732	WODH_2023_22
AM264313	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	31-Mar-23	F	80700401	9000	899995	EQ	4-Jun-23	6732	
AM261498	REPLACE EARTH STRAP IN THE ARTIC AREA RHS	1-Jun-23	F	80700401	9000		EQ	4-Jun-23	6732	
AM266526	REPLACE BLADE G.E.T	2-Jun-23	F	80700401	0050		EQ	2-Jun-23	6695	
AM263052	TWO WAY RADIO FAULTY	25-May-23	F	80700401	9000		EQ	25-May-23	6567	
AM241769	REPLACE TOP CIRCLE WEAR PADS AND SHIM TO CORRECT SPEC	18-May-23	F	80700401	0050		EQ	19-May-23	6537	WODH_2023_20
AM243599	REPLACE WORN BLADE SLIDES	18-May-23	F	80700401	0021		EQ	18-May-23	6537	WODH_2023_20
AM241773	REPLACE LIFT CYLINDER TOP CAPS, FIT NEW INSERTS AND SHIMS TO	18-May-23	F	80700401	7420-LH		EQ	18-May-23	6537	WODH_2023_20
AM260782	INVESTIGATE ENGINE LIGHT ON GRADER	17-May-23	F	80700401	1000		EQ	17-May-23	6526	
AM258361	A/C BLOWING WARM	13-May-23	F	80700401	9500		EQ	13-May-23	6473	
AM257212	FIRE SUPPRESSION LOW ON GAUGES	10-May-23	F	80700401	IN0705		EQ	10-May-23	6442	
AM256066	INVESTIGATE COOLANT LEAK	7-May-23	F	80700401	1000		EQ	7-May-23	6430	
AM251926	2 WAY RADIO CUTTING OUT AND A/C NOT COLD	27-Apr-23	F	80700401	9000		EQ	27-Apr-23	6363	
AM250214	REPLACE RH MISSING BLADE SLIDES	23-Apr-23	F	80700401	0050		EQ	23-Apr-23	6340	
AM250348	2 WAY RADIO NOT WORKING	23-Apr-23	F	80700401	9000		EQ	23-Apr-23	6340	
AM250191	MINE TWO WAY RADIO HAS BAD RECEPTION	23-Apr-23	F	80700401	9000		EQ	22-Apr-23	6340	
AM249486	REPLACE LH DOOR GLASS - ACCIDENT DAMAGE	21-Apr-23	F	80700401	0021		EQ	18-Apr-23	6305	
AM211711	16M - 18M BLADE SIDE SHIFT CYLINDER	17-Apr-23	F	80700760	7540	104575	EQ	17-Apr-23	6297	WODH_2023_16
AM175808	NDT STUB AXLE INSPECTIONS	16-Apr-23	F	80700401	IN8502	800015	EQ	17-Apr-23	6297	WODH_2023_15
AM092618	16M - 18M SEAT	17-Apr-23	F	80700401	8995	104582	EQ	17-Apr-23	6297	WODH_2023_16
AM246741	PRESTART #HV804805 SIDE SHIFT RAM LEAKING	14-May-23	F	80700401	INPRE	200000	EQ	16-Apr-23	6284	
AM241772	REPLACE 4 X DULL LIGHTS ON TOP OF CAB	2-May-23	F	80700401	0021		EQ	9-Apr-23	6252	
AM241766	TEST HARNESS ON ARTICULATION POSESTION SENSOR - NOT WORKING	2-May-23	F	80700401	7414		EQ	9-Apr-23	6252	
AM215826	PRESTART # REPLACE BLADE WEAR STRIPS FOUND TO BE U/S	3-Mar-23	F	80700760	0050	200000	EQ	9-Apr-23	6252	
AM199323	REPLACE TILT CYLINDER LINES	13-Mar-23	F	80700760	7000		EQ	9-Apr-23	6252	
AM166771	REPLACE BROKEN GREASE LINE, CIRCUIT BLOCKED	19-Nov-22	F	80269760	0091		EQ	9-Apr-23	6252	
AM199324	REPLACE BLADE SLIDE LINES	13-Mar-23	F	80700760	7000		EQ	9-Apr-23	6252	
AM243374	REPLACE POS 5 TYRE	8-Apr-23	F	80700401	TYRE		EQ	8-Apr-23	6252	
AM237993	CAT 16M - 18M GRADER 2000 HR PM SERVICE	13-Mar-23	F	80700401	P2000	900798	EQ	4-Apr-23	6199	
AM240216	REPLACE WORN BLADE GET	29-Mar-23	F	80700401	GET		EQ	29-Mar-23	6321	
AM161944	ENGINE BAY DOORS DAMAGED & MISSING	4-Nov-22	F	80269760	INPRE		EQ	21-Mar-23	6122	
AM216102	MOTOR GRADER 12 MONTH AFFV SERVICE	6-Mar-23	F	80700760	IN0707	800027	EQ	7-Mar-23	5954	
AM259630	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	28-Feb-23	F	80700401	9000	899995	EQ	28-Feb-23	5879	
AM209287	GREASE SYSTEM ALARM	19-Feb-23	F	80700760	0091		EQ	19-Feb-23	5849	
AM200716	REPLACE WORN CUTTING EDGES	16-Feb-23	F	80700760	GET		EQ	16-Feb-23	5821	
AM199241	REPLACE BATTERIES	12-Feb-23	F	80700760	9000		EQ	12-Feb-23	5799	
AM240761	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	31-Jan-23	F	80700401	9000	899995	EQ	31-Jan-23	5764	
AM191442	INSTALL TWO WAY RADIO WADGINA SPEC	17-Jan-23	F	80269760	9000		EQ	27-Jan-23	5717	
AM193726	SITE MOBILISATION AND ON-HIRE INSPECTION	26-Jan-23	F	80269760	INSP		EQ	27-Jan-23	5717	
AM187649	ELECTRICAL FAULT NO CAB A/C FAN	3-Jan-23	F	80269760	9000		EQ	3-Jan-23	5686	
AM099578	CHANGE OUT CONDENSOR FANS	29-May-22	F	80269760	1320		EQ	2-Jan-23	5668	
AM187406	AIR CON FAULT, CONDENSOR BLOCKED,FAN NOT OPERATING	1-Jan-23	F	80269760	9500		EQ	1-Jan-23	5668	
AM166598	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	30-Dec-22	F	80269760	9000	899995	EQ	31-Dec-22	5650	B4_2022_52
AM169538	CAT 16M - 18M GRADER 500 HR PM SERVICE	30-Dec-22	F	80269760	P0500	900796	EQ	29-Dec-22	5638	B4_2022_52
AM177516	C LAB-52329-V107 ENGINE OIL HIGH IRON REFER BELOW	30-Dec-22	F	80269760	1000		EQ	29-Dec-22	5611	B4_2022_52
AM185165	LHS TANDEM LOCKING UP	27-Dec-22	F	80269760	3210-RH		EQ	27-Dec-22	5595	
AM185159	LOWER BLADE SLIDE MISSING	27-Dec-22	F	80269760	0050		EQ	27-Dec-22	5595	
AM184230	REPLACE BLADE CUTTING EDGES	26-Dec-22	F	80269760	GET		EQ	26-Dec-22	5595	
AM182710	INVESTIGATE AND REPAIR BENT TRANSMISSION BELLY GUARD	18-Dec-22	F	80269760	8000		EQ	19-Dec-22	5490	
AM138777	PRESTART # BOTH SIDES BOARDING STEPS BENT	15-Nov-22	F	80269760	INPRE	200000	EQ	16-Dec-22	5431	B4_2022_46
AM181545	BATTERY LIGHT ON	14-Dec-22	F	80269760	9000		EQ	15-Dec-22	5412	
AM180245	OPERATOR TWISTED SEAT BELT	10-Dec-22	F	80269760	8995		EQ	10-Dec-22	5403	
AM179606	INSPECT AND REPAIR DOOR ALARM	8-Dec-22	F	80269760	9000		EQ	8-Dec-22	5395	
AM179338	REPLACE CUTTING EDGES	7-Dec-22	F	80269760	GET		EQ	7-Dec-22	5371	
AM179296	A/C CUTTING IN AND OUT	6-Dec-22	F	80269760	9500		EQ	6-Dec-22	5370	
AM178590	INVESTIGATE AND REPAIR WARM A/C	5-Dec-22	F	80269760	9500		EQ	4-Dec-22	5341	
AM178343	REPAIR OIL LEAK AT BLADE ROLL CYLINDER	3-Dec-22	F	80269760	7000		EQ	3-Dec-22	5306	

Work Order	Description	Start Date	Status	Cost Centre	Comp Code	PM Task	Branch	Finish Date	Done @	Schedule Week
AM166932	REPLACE BROKEN GREASE LINE	20-Nov-22	F	80269760	MISC		EQ	20-Nov-22	5162	
AM166692	INVESTIGATE LOOSE SEAT BASE	19-Nov-22	F	80269760	8995		EQ	19-Nov-22	5162	
AM165912	ACC DAMAGE - LHR ACCESS LADDER DAMAGED	16-Nov-22	F	80269760	8000		EQ	16-Nov-22	5115	
AM107677	CHANGE OUT FITTINGS ON STEER CYLINDER TO OEM FITTINGS	15-Nov-22	F	80269760	4110		EQ	15-Nov-22	5112	B4_2022_46
AM136642	PRESTART # ARTIC GAUGE REQUIRES CALIBRATIONS	6-Oct-22	F	80269760	INPRE	200000	EQ	15-Nov-22	5112	B4_2022_40
AM106904	REPLACE BLADE LIFT CYLINDER INSERTS/CUPS, LH CYLINDER HAS	15-Nov-22	F	80269760	7420-RH		EQ	15-Nov-22	5112	B4_2022_46
AM086716	PRESTART # FAULTY LADDER ISOLATION BOX SHUT WITH ROPE	15-Nov-22	F	80269760	INPRE	200000	EQ	15-Nov-22	5112	B4_2022_46
AM025141	INSTALL NEW GREASE PUMP BRACKET	15-Nov-22	F	80263760	0091		EQ	15-Nov-22	5112	B4_2022_46
AM139219	REPLACE HANDRAIL LHS REAR ACCESS LADDER	15-Nov-22	F	80269760	0021		EQ	15-Nov-22	5112	B4_2022_46
AM153547	CAT 16M - 18M GRADER 1000 HR PM SERVICE	15-Nov-22	F	80269760	P1000	900797	EQ	15-Nov-22	5112	B4_2022_46
AM159798	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	15-Nov-22	F	80269760	9000	899995	EQ	15-Nov-22	5112	B4_2022_46
AM164038	REPLACE CUTTING EDGES	10-Nov-22	F	80269760	GET		EQ	14-Nov-22	5088	
AM164630	LOWER BLADE SLIDES MISSING	11-Nov-22	F	80269760	0050		EQ	11-Nov-22	5088	
AM115490	NDT STUB AXLE INSPECTIONS	10-Nov-22	F	80269760	IN8502	800015	EQ	10-Nov-22	5088	B4_2022_45
AM160487	RETORQUE P 4 & 6 AFTER TANDEM REPAIRS	30-Oct-22	F	80269760	TYRE		EQ	30-Oct-22	4907	
AM159123	16M - 18M TANDEM CHAIN RIGHT	27-Oct-22	F	80269760	3210-RH		EQ	30-Oct-22	4907	
AM158476	REPLACE WORN BLADE G.E.T	25-Oct-22	F	80269760	GET		EQ	26-Oct-22	4900	
AM158365	REPAIRS TO DAMAGED SEAT BELT WARNING HARNESS	26-Oct-22	F	80269760	9000		EQ	25-Oct-22	4900	
AM154843	PRESTART # ENGINE BAY DOORS DAMAGED & MISSING	17-Oct-22	F	80269760	INPRE	200000	EQ	25-Oct-22	4891	
AM156857	ENGINE DERATE AIR FILTER RESTRICTION	23-Oct-22	F	80269760	1000		EQ	22-Oct-22	4846	
AM156684	INVESTIGATE OIL LEAK AROUND TANDEM. LOOSE BRAKE PIPE FITTING	22-Oct-22	F	80269760	7000		EQ	21-Oct-22	4832	
AM129529	REPAIR MACHINE DOOR - WESTRAC NEWMAN	28-Aug-22	F	80269760	0021		EQ	15-Oct-22	4729	
AM117346	UPGRADE LIGHTS	1-Jul-22	F	80269760	9000		EQ	15-Oct-22	4729	
AM091279	WESTRAC NEWMAN TO CARRY OUT MULTIPLE REPAIRS AS QUOTED	30-Apr-22	F	80269760	MISC		EQ	15-Oct-22	4729	
AM112237	REPLACE WORK LED LIGHTS AND HEAD LIGHT GLOBES	4-Jul-22	F	80269760	9000		EQ	15-Oct-22	4729	
AM153056	RESEAL FRONT WINDSCREEN, DUST ENTERING	10-Oct-22	F	80269760	0021		EQ	10-Oct-22	4690	
AM152133	REPLACE CUTTING EDGES GET	8-Oct-22	F	80269760	GET		EQ	8-Oct-22	4650	
AM143175	CAT 16M - 18M GRADER 500 HR PM SERVICE	6-Oct-22	F	80269760	P0500	900796	EQ	6-Oct-22	4644	B4_2022_40
AM136640	PRESTART # 2 WAY SPEAKER IS LOOSE	6-Oct-22	F	80269760	INPRE	200000	EQ	5-Oct-22	4644	B4_2022_40
AM149258	C/O CUTTING EDGES	28-Sep-22	F	80269760	GET		EQ	28-Sep-22	4515	
AM149291	REPLACE DEFECTIVE, DULL LEDS	28-Sep-22	F	80269760	9000		EQ	28-Sep-22	4515	
AM147817	ECM FAULT ACTIVE, MACHINE WON'T START	24-Sep-22	F	80269760	9000		EQ	24-Sep-22	4466	
AM147672	INSPECT AUTO LUBE SYSTEM, OPEARTOR REPORTS MACHINE DRY	24-Oct-22	F	80269760	0091		EQ	24-Sep-22	4460	
AM147610	REPLACE WORN BLADE SLIDES	23-Sep-22	F	80269760	0050		EQ	23-Sep-22	4449	
AM147608	E STOP FALLEN OUT	23-Sep-22	F	80269760	9000		EQ	23-Sep-22	4449	
AM141614	REPLACE LOWER BLADE SLIDE	5-Sep-22	F	80269760	0050		EQ	19-Sep-22	4390	
AM142328	LH TANDEM FILLING WITH HYDRAULIC OIL	6-Sep-22	F	80269760	3000		EQ	19-Sep-22	4390	
AM146335	MOTOR GRADER 6 MONTH AFF SERVICE	19-Sep-22	F	80269760	IN0706	800026	EQ	19-Sep-22	4374	
AM141567	REPLACE FRONT HEADLIGHTS	4-Sep-22	F	80269760	9000		EQ	6-Sep-22	4373	
AM141331	REPLACE WORN CUTTING EDGES	3-Sep-22	F	80269760	GET		EQ	4-Sep-22	4342	
AM139623	SPEAKER BRACKET BROKEN	30-Aug-22	F	80269760	MISC		EQ	29-Aug-22	4239	
AM138342	REAR MUDGAURD BOLTS LOOSE AND MOUNT CRACKED	24-Aug-22	F	80269760	0021		EQ	24-Aug-22	4192	
AM138014	CUTTING EDGES WORN & REQUIRE REPLACING	23-Aug-22	F	80269760	0050		EQ	24-Aug-22	4192	
AM138555	REPAIR HYDRAULIC OIL LEAK AT POS 1	24-Aug-22	F	80269760	7000		EQ	24-Aug-22	4192	
AM138345	REPLACE 2 X FRONT WORK LIGHTS WHICH WERE DULL	23-Aug-22	F	80269760	9000		EQ	23-Aug-22	4186	
AM133824	PRE START MACHINE INSPECTION	13-Aug-22	F	80269760	INSP		EQ	13-Aug-22	4084	
AM118569	16M - 18M TRANSMISSION (FAILED 24/6/2022 @ 4069HRS)	24-Jun-22	F	80269760	2000	104546	EQ	24-Jun-22	4069	
AM109265	CAT 16M - 18M GRADER 2000 HR PM SERVICE	23-Jun-22	F	80269760	P2000	900798	EQ	24-Jun-22	4071	B4_2022_25
AM116209	TRANSMISSION FILTER BLOCKAGE	20-Jun-22	F	80269760	2000		EQ	20-Jun-22	4035	
AM115341	TRANSMISSION FILTER RESTRICTION	16-Jun-22	F	80269760	2000		EQ	17-Jun-22	3998	
AM115323	BLADE SLIDES U/S	16-Jun-22	F	80269760	GET		EQ	16-Jun-22	3998	
AM114568	HYDRAULIC OIL LEAK	14-Jun-22	F	80269760	7000		EQ	14-Jun-22	4003	
AM113895	REPAIR HYD LEAK AND TOP UP HYD OIL	13-Jun-22	F	80269760	7000		EQ	13-Jun-22	3976	
AM113902	A/C BLOWING HOT AND COLD.	13-Jun-22	F	80269760	9500		EQ	13-Jun-22	3976	
AM115108	PARK BRAKE FAULT	15-Jun-22	F	80269760	9000		EQ	12-Jun-22	3976	
AM113255	REPAIR HYD OIL LEAK ON RH STEERING CYLINDER	10-Jun-22	F	80269760	7000		EQ	10-Jun-22	3976	
AM113333	FIRE SUPPRESSION PRESSURE LOW	10-Jun-22	F	80269760	IN0705		EQ	10-Jun-22	3976	
AM111828	REPLACE WORN CUTTING EDGES	5-Jun-22	F	80269760	GET		EQ	5-Jun-22	3868	
AM111768	REPLACE BLADE CUTTING EDGES	5-Jun-22	F	80269760	GET		EQ	5-Jun-22	3837	
AM111585	REPLACE BLADE SLIDES	4-Jun-22	F	80269760	0050		EQ	4-Jun-22	3852	
AM111722	REPAIR WORK LIGHTS	4-Jun-22	F	80269760	9000		EQ	4-Jun-22	3837	
AM109514	REPALCE CUTTING EDGES	29-May-22	F	80269760	GET		EQ	29-May-22	3794	
AM106820	P2 STEERING CYLINDER FITTING BROKEN	17-May-22	F	80269760	7000		EQ	17-May-22	3676	
AM087121	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	15-May-22	F	80269760	9000	899995	EQ	15-May-22	3646	B4_2022_19
AM080942	COOLANT CHANGE OUT AS PER ATTACHED PROCEDURE	15-May-22	F	80269760	1310	400000	EQ	15-May-22	3646	B4_2022_19
AM079820	C LAB-52006-3233 ENGINE OIL HIGH IRON AND COPPER.	15-May-22	F	80269760	1000		EQ	15-May-22	3646	B4_2022_19
AM104455	REPLACE MISSING BOLT ON GUARD RAIL	11-May-22	F	80269760	MISC		EQ	11-May-22	3612	
AM104405	AIR CON BLOWING WARM	11-May-22	F	80269760	9500		EQ	11-May-22	3612	
AM104402	ENGINE FAULT LIGHT ON	11-May-22	F	80269760	1000		EQ	11-May-22	3612	
AM103578	AIR CON BLOWING WARM	9-May-22	F	80269760	9500		EQ	9-May-22	3599	
AM103577	LADDER HIT AND PULLED DOWN STOPPING HYDRAULIC FUNCTIONS	9-May-22	F	80269760	0021		EQ	9-May-22	3601	
AM079407	CAT 16M - 18M GRADER 500 HR PM SERVICE	9-May-22	F	80269760	P0500	900796	EQ	9-May-22	3601	B4_2022_19
AM103200	REPLACE CUTTING EDGES	8-May-22	F	80269760	GET		EQ	8-May-22	3599	
AM102149	ELECTRICAL FAULTS - LIGHTING SYSTEM	5-May-22	F	80269760	9000		EQ	5-May-22	3557	
AM101167	HAND RAIL MISSING BOLT	4-May-22	F	80269760	MISC		EQ	4-May-22	3557	
AM099449	AIR CONDITIONING U/S	29-Apr-22	F	80269760	9500		EQ	30-Apr-22	3499	
AM081000	NDT STUB AXLE INSPECTIONS	29-Apr-22	F	80269760	IN8502	800015	EQ	29-Apr-22	3490	B4_2022_17
AM099044	HEADLIGHTS NOT WORKING	28-Apr-22	F	80269760	9000		EQ	28-Apr-22	3482	
AM097971	REPAIR A/C	27-Apr-22	F	80269760	9000		EQ	27-Apr-22	3443	
AM097969	REPAIR COOLANT LEAK	27-Apr-22	F	80269760	1000		EQ	27-Apr-22	3443	
AM086549	TRANSMISSION WILL NOT SELECT 4TH GEAR	16-Mar-22	F	80269760	2000		EQ	16-Mar-22	3414	
AM086746	16M - 18M TRANSMISSION (FAILED 16/3/2022)	16-Mar-22	F	80269760	2000	104546	EQ	16-Mar-22	3410	

Work Order	Description	Start Date	Status	Cost Centre	Comp Code	PM Task	Branch	Finish Date	Done @	Schedule Week
AM079454	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	11-Mar-22	F	80269760	9000	899995	EQ	14-Mar-22	3355	B4_2022_10
AM086125	REPLACE CUTTING EDGES AND BLADE SLIDES	14-Mar-22	F	80269760	GET		EQ	14-Mar-22	3355	
AM085231	REPLACE 2 FLAT TYRES WITH RUNOUTS	11-Mar-22	F	80269760	TYRE		EQ	11-Mar-22	3330	
AM029207	MOTOR GRADER 12 MONTH AFF SERVICE	5-Mar-22	F	80263760	IN0707	800027	EQ	7-Mar-22	3269	B4_2022_09
AM083988	REPLACE FAILED A/C COMPRESSOR	7-Mar-22	F	80269760	9500		EQ	7-Mar-22	3278	
AM083130	HYDRAULIC FAULT	4-Mar-22	F	80269760	7000		EQ	4-Mar-22	3269	
AM080886	CHANGE POS 3, 4, 5 & 6 TYRES	3-Mar-22	F	80269760	TYRE		EQ	3-Mar-22	3269	
AM082796	REPLACE MISSING BLADE SLIDE	2-Mar-22	F	80269760	0050		EQ	2-Mar-22	3269	
AM080925	16M - 18M ARTICULATION CYLINDER LEFT	27-Feb-22	F	80269760	7414-LH	104576	EQ	1-Mar-22	3257	
AM080905	DIAGNOSE AND RECTIFY 2085 ARTICULATION SENSOR FAULT	25-Feb-22	F	80269760	7000		EQ	25-Feb-22	3257	
AM080527	CHANGE OUT GET	22-Mar-22	F	80269760	GET		EQ	22-Feb-22	3205	
AM079849	REPAIR WORK LIGHTS	20-Feb-22	F	80269760	9000		EQ	20-Feb-22	3205	
AM079575	REPAIR LEAKING STEERING HOSE	19-Feb-22	F	80269760	7000		EQ	19-Feb-22	3205	
AM078698	REMOVE FAILED HOSES MAKE UP NEW HOSE AND REFIT.	15-Feb-22	F	80269760	7000		EQ	15-Feb-22	3091	
AM078654	DIAGNOSE AIRCON FAULT	14-Feb-22	F	80269760	9500		EQ	14-Feb-22	3044	
AM078252	STEERING PUMP PRESSURE LOW FAULT	13-Feb-22	F	80269760	4110		EQ	13-Feb-22	3044	
AM073761	REPLACE ALL BLADE SLIDES, SHIMS, RETAINER PLATES, NUTS,	10-Feb-22	F	80269760	0050		EQ	13-Feb-22	3044	B4_2022_06
AM078251	REPLACE BLADE GET	13-Feb-22	F	80269760	GET		EQ	13-Feb-22	3044	
AM071592	CAT 16M - 18M GRADER 1000 HR PM SERVICE	10-Feb-22	F	80269760	P1000	900797	EQ	12-Feb-22	3034	B4_2022_06
AM033446	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	10-Feb-22	F	80263760	9000	899995	EQ	11-Feb-22	3034	B4_2022_06
AM070048	X LAB SAMPLE-52007-1314 HYDRAULIC OIL HAS HIGH IRON	10-Feb-22	F	80263760	7000		EQ	11-Feb-22	3034	B4_2022_06
AM076802	REPLACE MISSING BLADE SLIDE	9-Feb-22	F	80269760	0050		EQ	8-Feb-22	3000	
AM073708	REPLACE CUTTING EDGES	29-Jan-22	F	80269760	GET		EQ	29-Jan-22	2876	
AM072937	REPLACE FULL SET OF BLADE SLIDES	26-Jan-22	F	80269760	0050		EQ	26-Jan-22	2833	
AM072597	FIT TOP BLADE SLIDES	24-Jan-22	F	80269760	0050		EQ	24-Jan-22	2805	
AM053287	NDT STUB AXLE INSPECTIONS	7-Jan-22	F	80263760	IN8502	800015	EQ	6-Jan-22	2560	
AM055408	CAT 16M - 18M GRADER 500 HR PM SERVICE	25-Dec-21	F	80263760	P0500	900796	EQ	25-Dec-21	2506	B2_2021_52
AM062998	REPLACE BROKEN BLADE SLIDE	19-Dec-21	F	80263760	GET		EQ	19-Dec-21	2398	
AM062099	REPLACE CUTTING EDGES	15-Dec-21	F	80263760	GET		EQ	15-Dec-21	2338	
AM061909	INSPECT MACHINE, REPORTED HYDRAULIC NOISE	14-Dec-21	F	80263760	7000		EQ	14-Dec-21	2336	
AM058294	REPLACE CUTTING EDGES	5-Dec-21	F	80263760	GET		EQ	4-Dec-21	2171	
AM054874	REPLACE WORN CUTTING EDGES	24-Nov-21	F	80263760	GET		EQ	24-Nov-21	2037	
AM054293	16M - 18M LIFT/HOIST CYLINDER RIGHT	22-Nov-21	F	80263760	7420-RH	104569	EQ	24-Nov-21	2037	
AM054340	16M - 18M LIFT/HOIST CYLINDER LEFT	23-Nov-21	F	80263760	7420-LH	104568	EQ	24-Nov-21	2037	
AM050501	INSPECT ALL MACHINE MOUNTED HYDRAULIC LADDERS FOR	19-Nov-21	F	80263760	7000		EQ	20-Nov-21	2008	B2_2021_47
AM050058	CAT 16M - 18M GRADER 2000 HR PM SERVICE	19-Nov-21	F	80263760	P2000	900798	EQ	19-Nov-21	1995	B2_2021_47
AM049837	FORMATTING THE SD CARD CORRECTLY FOR BLACKVUE CAMERAS WILL	19-Nov-21	F	80263760	9000		EQ	19-Nov-21	1995	B2_2021_47
AM050731	PRESTART ; AE72131 REVERSE CAMERA NOT WORKING	19-Nov-21	F	80263760	INPRE		EQ	19-Nov-21	1995	B2_2021_47
AM041721	PRSTART : HV557841 GREASE LINE BROKEN REAR POS 1	19-Nov-21	F	80263760	INPRE		EQ	19-Nov-21	1995	B2_2021_47
AM051193	CHANGE FROM 5 SPEED TO 7 SPEED	14-Nov-21	F	80263760	9000		EQ	9-Nov-21	1823	B2_2021_46
AM050653	A/C NOT WORKING	6-Nov-21	F	80263760	9500		EQ	5-Nov-21	1781	
AM049313	REPLACE CUTTING EDGES	1-Nov-21	F	80263760	GET		EQ	1-Nov-21	1735	
AM047297	HYDRAULICS LOCKED OUT. FOUND FAILED LADDER PROXIMITY SWITCH.	26-Oct-21	F	80263760	9000		EQ	27-Oct-21	1672	
AM045464	PARK BRAKE/DOOR ALARM FAULT	22-Oct-21	F	80263760	9000		EQ	21-Oct-21	1600	
AM044671	FIRE SUPPRESSION FAULT	20-Oct-21	F	80263760	9000		EQ	19-Oct-21	1577	
AM043855	GREASE SYSTEM FAULT	16-Oct-21	F	80263760	0091		EQ	16-Oct-21	1541	
AM041683	FIRE SUPPRESSION ALARM GOING OFF	9-Oct-21	F	80263760	9500		EQ	9-Oct-21	1502	
AM041415	REPLACE WORN G.E.T	7-Oct-21	F	80263760	GET		EQ	7-Oct-21	1487	
AM027164	CAT 16M - 18M GRADER 500 HR PM SERVICE	2-Oct-21	F	80263760	P0500	900796	EQ	3-Oct-21	1461	B2_2021_40
AM035584	REPLACE ACCESS LADDER ON LH SIDE	15-Sep-21	F	80263760	8000		EQ	15-Sep-21	1276	
AM034679	C/O CUTTING EDGES AND SLIDES	13-Sep-21	F	80263760	GET		EQ	13-Sep-21	1263	
AM033894	INSPECT AUTO LUBE SYSTEM FAULT	11-Sep-21	F	80263760	0091		EQ	11-Sep-21	1239	
AM033519	REPAIR DAMAGED RHS LOWER BLADE SLIDE MOUNT	10-Sep-21	F	80263760	0050		EQ	10-Sep-21	1235	
AM033339	BROKEN GREASE LINE ON STEERING BALL JOINT	8-Sep-21	F	80263760	4110		EQ	8-Sep-21	1213	
AM019246	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	7-Sep-21	F	80263760	9000	899995	EQ	7-Sep-21	1192	B2_2021_36
AM020893	PRESTART : AE20338 BOTTOM LEFT BATTEN MISSING	19-Nov-21	F	80263760	INPRE		EQ	3-Sep-21	1150	B2_2021_47
AM031557	REPLACE U/S BATTERIES	2-Sep-21	F	80263760	9000		EQ	2-Sep-21	1122	
AM031784	AFFF DISCHARGED	2-Sep-21	F	80263760	9000		EQ	2-Sep-21	1160	
AM031028	REPLACE DAMAGED LHS LOWER BLADE SLIDE AND RETAINER	30-Aug-21	F	80263760	0050		EQ	30-Aug-21	1098	
AM029630	TIGHTEN FRONT LIGHTS AND GREASE BULK FILL FITTING	29-Aug-21	F	80263760	0021		EQ	29-Aug-21	1079	
AM029529	TEMPORARILY REPAIR LHS ACCESS LADDER	27-Aug-21	F	80263760	0021		EQ	27-Aug-21	1067	
AM027905	PRESTART #LV366069 GET LOOSE ON BLADE	17-Sep-21	F	80263760	INPRE	200000	EQ	27-Aug-21	1062	
AM029429	LADDER KEEPS GOING DOWN	28-Aug-21	F	80263760	7000		EQ	27-Aug-21	1062	
AM029123	REPLACE CUTTING EDGES	26-Aug-21	F	80263760	GET		EQ	26-Aug-21	1048	
AM025489	MOTOR GRADER 6 MONTH AFF SERVICE	2-Oct-21	F	80263760	IN0706	800026	EQ	24-Aug-21	1028	B2_2021_35
AM017051	PRESTART #AE20327 L/H Lift Cyl Bolt to clamp Hose missing	12-Aug-21	F	80263760	INPRE	200000	EQ	12-Aug-21	924	B2_2021_33
AM017227	CAT 16M - 18M GRADER 1000 HR PM SERVICE	12-Aug-21	F	80263760	P1000	900797	EQ	12-Aug-21	924	B2_2021_33
AM022432	RESEAL RHS WINDOW ON CAB	2-Aug-21	F	80263760	0021		EQ	2-Aug-21	845	
AM022155	REPLACE BLADE SLIDES	1-Aug-21	F	80263760	0050		EQ	1-Aug-21	830	
AM020258	LOST LEFT HAND BLADE SLIDE	26-Jul-21	F	80263760	0050		EQ	25-Jul-21	744	
AM018334	REPLACE WORN CUTTING EDGES	19-Aug-21	F	80263760	GET		EQ	19-Jul-21	744	
AM008632	16M - 18M TANDEM CHAIN LEFT - SNAPPED CHAIN & DAMAGED GEAR	1-Jul-21	F	80263760	3210-LH	104552	EQ	8-Jul-21	627	
AM006141	BLADE SLIDES MISSING, NOT REPORTED, FOUND AT REFUEL	19-Jun-21	F	80263760	0050		EQ	26-Jun-21	590	
AM005551	CHANGE OUT GET BLADE	15-Jul-21	F	80263760	0050		EQ	26-Jun-21	595	
AM006640	GREASE PUMP IMCORRECTLY INSTALLED CAUSING PUMP TO CONTACT	21-Jun-21	F	80263760	0091		EQ	21-Jun-21	492	
AM002126	REPLACE RHS SMASHED WINDOW	5-Jun-21	F	80263760	0021		EQ	7-Jun-21	417.8	
00185099	CAT 16M - 18M GRADER 500 HR PM SERVICE	31-May-21	F	80263760	P0500	900796	EQ	1-Jun-21	417.8	B2_2021_22
00167374	SITE MOBILISATION AND ON-HIRE INSPECTION	17-Feb-21	F	80070760	INSP		001	9-May-21	272	
00186681	MACHINE DOWN - REPLACE STARTER MOTOR	6-May-21	F	80263760	9000		EQ	6-May-21	272	