

Work Order	Description	Start Date	Status	Cost Centre	Comp Code	PM Task	Branch	Finish Date	Done @	Schedule Week
AM440195	1M INSPECTION CONTATORE TYRE HANDLER ATTACHMENT	25-May-24	F	80700401	INMTH	800478	EQ	24-May-24	7172	WODW_2024_21
AM440086	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	25-May-24	F	80700401	9000	899995	EQ	24-May-24	7172	WODW_2024_21
WL036709	INSPECT AND REPAIR TYRE HANDLING ATTACHMENT	25-May-24	F	80700401	7000		EQ	24-May-24	7172	WODW_2024_21
AM317969	PRESTART - R/H SIDE PANEL UNABLE TO CLOSE	25-May-24	F	80710401	INPRE		EQ	24-May-24	7172	WODW_2024_21
AM317967	PRESTART - INSPECT ALL WORKLIGHTS AND REPLACE AS REQUIRED	25-May-24	F	80710401	INPRE		EQ	24-May-24	7172	WODW_2024_21
AM317968	PRESTART - INSPECT WINDSHEILD CRACK	25-May-24	F	80710401	INPRE		EQ	24-May-24	7172	WODW_2024_21
004869	OVERHAUL A/C SYSTEM	21-May-23	F	80700401	9000		EQ	29-Mar-24	7172	
AM351056	982M / 982 INSPECT RIDE CONTROL ACCUMULATOR POS 2	23-Mar-23	F	80710401	7646	700135	EQ	23-Mar-24	7172	
AM345810	982M / 982 INSPECT RIDE CONTROL ACCUMULATOR POS 1	23-Mar-24	F	80710401	7646	700134	EQ	23-Mar-24	7172	
AM342000	6 MONTH WHEEL LOADER FIRE SUPPRESSION SERVICE AFFF	30-Jan-24	F	80710401	IN0706	800032	EQ	30-Jan-24	7172	WODG_2024_05
WL034781	CONTATORE TYRE HANDLER ATTACHMENT MONTHLY INSPECTION	22-Dec-23	F	41700412	INMTH	800478	LIT	15-Dec-23	7165	
WL034397	WHEEL LOADER 12 MONTH AFFF SERVICE	14-Dec-23	F	41700412	IN0707	800033	LIT	14-Dec-23	7165	WODG_2023_50
WL033535	CONTATORE TYRE HANDLER ATTACHMENT MONTHLY INSPECTION	22-Nov-23	F	41700412	INMTH	800478	LIT	23-Nov-23	7165	WODG_2023_47
WL030722	CAT 982M LOADER 500 HR SERVICE	8-Nov-23	F	41700412	P0500	900015	LIT	9-Nov-23	7164	WODG_2023_45
WL031775	CONTATORE TYRE HANDLER ATTACHMENT MONTHLY INSPECTION	8-Nov-23	F	41700412	INMTH	800478	LIT	8-Nov-23	7164	WODG_2023_45
AM317885	PRESTART #051703 AUTO LUBE FAULT	22-Oct-23	F	80710401	INPRE	200000	EQ	22-Oct-23	7150	
AM151391	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	11-Oct-23	F	80700760	9000	899995	EQ	12-Oct-23	7150	MTM_2023_41
AM153120	CAT 982M LOADER 500 HR SERVICE REQ 558295	11-Oct-23	F	80700760	P0500	900015	EQ	11-Oct-23	7150	MTM_2023_41
AM286170	1M INSPECTION CONTATORE TYRE HANDLER ATTACHMENT	22-Sep-23	F	80710401	INMTH	800478	EQ	22-Sep-23	7147	MTM_2023_38
AM305311	PRESTART #049917 AUTO LUBE FAULT	5-Sep-23	F	80710401	INPRE	200000	EQ	5-Sep-23	7114	MTM_2023_36
AM298040	INSPECT AND DIAGNOSE WHY AUTO LUBE SYSTEM NOT WORKING	5-Sep-23	F	80710401	0091		EQ	5-Sep-23	7114	MTM_2023_36
AM302918	PRESTART # 49906 HEATER DOES NOT WORK	5-Sep-23	F	80710401	INPRE	200000	EQ	5-Sep-23	7109	MTM_2023_36
AM296458	*2 WAY RADIO REQUIRES REPROGRAMMING; CURRENTLY PROGRAMMED	3-Sep-23	F	80710401	9000		EQ	3-Sep-23	7100	
AM286134	1M INSPECTION CONTATORE TYRE HANDLER ATTACHMENT	23-Aug-23	F	80710401	INMTH	800478	EQ	23-Aug-23	7081	MTM_2023_34
AM159356	WHEEL LOADER 12 MONTH AFFF SERVICE	2-Aug-23	F	80700401	IN0707	800033	EQ	4-Aug-23	7033.5	MTM_2023_31
WL029891	INSPECT GREASE RECEIVER COUPLINGS FOR SERVICEABILITY	2-Aug-23	F	80700401	0091		EQ	2-Aug-23	7009	
AM286065	1M INSPECTION CONTATORE TYRE HANDLER ATTACHMENT	2-Aug-23	F	80710401	INMTH	800478	EQ	2-Aug-23	7033	MTM_2023_31
WL027813	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	18-Nov-22	F	41700412	9000	899995	LIT	18-Jul-23	6927	
WL018421	CONTATORE TYRE HANDLER ATTACHMENT MONTHLY INSPECTION	22-Apr-23	F	80700401	INMTH	800478	EQ	18-Jul-23	6927	
AM176547	CONTATORE TYRE HANDLER ATTACHMENT MONTHLY INSPECTION	22-Feb-23	F	41700412	INMTH	800478	LIT	18-Jul-23	6927	
AM168791	REPLACE HYDRAULIC HOSES LEAKING	25-Nov-22	F	80700760	7000		EQ	14-Jul-23		
WL026508	WHEEL LOADER 6 MONTH AFFF SERVICE	9-Jun-23	F	41700412	IN0706	800032	LIT	17-Jun-23	6927	
WL018809	CONTATORE TYRE HANDLER ATTACHMENT MONTHLY INSPECTION	21-May-23	F	41700412	INMTH	800478	LIT	21-May-23	6916	WODG_2023_20
WL011412	BD - TYRE HANDLER ALARM ACTIVE	4-Mar-23	F	80700401	9000		EQ	4-Mar-23	6861	
WL006731	L/H GRAB PAD EXCESSIVE MOVEMENT	1-Feb-23	F	41700412	8000		LIT	1-Feb-23	6836	
AM175215	CONTATORE TYRE HANDLER ATTACHMENT MONTHLY INSPECTION	11-Jan-23	F	41700412	INSP	800478	LIT	12-Jan-23	6812	
004158	PRESTART # HV721508 AIRCON CYCLES HOT THEN COLD	12-Jan-23	F	41700412	INPRE	200000	LIT	12-Jan-23	6808	WODG_2023_02
AM160592	CONTATORE TYRE HANDLER ATTACHMENT MONTHLY INSPECTION	23-Nov-22	F	80700760	INMTH	800478	EQ	23-Nov-22	6743	WODG_2022_47
AM120744	REPLACE A/C CONTROL PANEL	12-Nov-22	F	80700760	9500		EQ	12-Nov-22	6736	WODG_2022_45
AM146805	CONTATORE TYRE HANDLER ATTACHMENT MONTHLY INSPECTION	12-Nov-22	F	80700760	INMTH	800478	EQ	12-Nov-22	6736	WODG_2022_45
AM042084	REPLACE DAMAGED FRONT FENDER	12-Nov-22	F	80249760	0021		EQ	12-Nov-22	6736	WODG_2022_45
AM139044	REPLACE BLACKVIEW	2-Nov-22	F	80700760	MISC		EQ	5-Nov-22	6722	WODG_2022_44
AM041618	982M TURBOCHARGER & WATERPUMP *	10-Oct-22	F	80249760	1004	100997	EQ	13-Oct-22	6706	WODG_2022_40
AM100334	LOADRITE CALIBRATION	29-Sep-22	F	80700760	INSP	800016	EQ	29-Sep-22	6698	WODG_2022_39
AM140134	CAT 982M LOADER 1000 HR SERVICE	18-Sep-22	F	80700760	P1000	900016	EQ	18-Sep-22	6695	WODG_2022_37
AM132317	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	18-Sep-22	F	80700760	9000	899995	EQ	18-Sep-22	6695	WODG_2022_37
AM137743	CONTATORE TYRE HANDLER ATTACHMENT MONTHLY INSPECTION	18-Sep-22	F	80700760	INMTH	800478	EQ	18-Sep-22	6695	WODG_2022_37
AM124017	CONTATORE TYRE HANDLER ATTACHMENT MONTHLY INSPECTION	20-Aug-22	F	80700760	INMTH	800478	EQ	20-Aug-22	6628	WODG_2022_33
AM123582	PRESTART # FUES BLONW ON ATTACHMENT COUSING LOSS OF FUNCTION	20-Jul-22	F	80700760	INPRE	200000	EQ	20-Jul-22	6610	WODG_2022_29
AM123583	PRESTART # LIGHT ON ATTACHMENT NEEDS NEW BRACKET	20-Jul-22	F	80700760	INPRE	200000	EQ	20-Jul-22	6610	WODG_2022_29
AM118857	CONTATORE TYRE HANDLER ATTACHMENT MONTHLY INSPECTION	20-Jul-22	F	80700760	INMTH	800478	EQ	20-Jul-22	6610	WODG_2022_29
AM100684	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	20-Jul-22	F	80700760	9000	899995	EQ	20-Jul-22	6610	WODG_2022_29
AM107264	PRESTART # GREASE LINE ON FRONT ARM PINS DAMAGED	20-Jul-22	F	80700760	INPRE	200000	EQ	20-Jul-22	6610	WODG_2022_29
AM100304	WHEEL LOADER 6 MONTH AFFF SERVICE	1-Jul-22	F	80700760	IN0706	800032	EQ	28-Jun-22	6602	WODG_2022_26
AM104743	ON HIRE INSPECTION	10-Jun-22	F	80700760	INSP		EQ	13-May-22	6577	
AM099028	INSTALL VHF 2WAY	28-Apr-22	F	80700760	9000		EQ	28-Apr-22	6577	
AM040675	WHEEL LOADER WEEKLY INSPECTION	16-Oct-21	F	80249760	INSP	800012	EQ	15-Oct-21	6535	ROYH_2021_42
AM040672	WHEEL LOADER WEEKLY INSPECTION	8-Oct-21	F	80249760	INSP	800012	EQ	9-Oct-21	6480	ROYH_2021_41
AM009937	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	1-Oct-21	F	80245760	9000	899995	EQ	4-Oct-21	6445	ROYH_2021_40
AM038401	WHEEL LOADER WEEKLY INSPECTION	1-Oct-21	F	80249760	INSP	800012	EQ	2-Oct-21	6415	ROYH_2021_40
00154515	LOADRITE CALIBRATION	1-Jun-21	F	80245760	MISC	800016	EQ	9-Sep-21	6392	KOOL_2021_23
AM000174	982M SEAT	1-Jul-21	F	80245760	8995	101031	EQ	2-Sep-21	6392	
AM009946	K-JPS SLIP JOINT ON FRONT DRIVE SHAFT IS WORN	2-Aug-21	F	80245760	3000		EQ	1-Sep-21	6392	
AM006013	CAT 982M LOADER 500 HR SERVICE #	15-Jul-21	F	80245760	P0500	900015	EQ	30-Aug-21	6392	
AM004097	REPLACE BONNET ACTUATORS	4-Jul-21	F	80245760	9000		EQ	30-Aug-21	6392	KOOL_2021_27
00191409	982M TRUNNION	2-Jul-21	F	80245760	8430	101030	EQ	30-Aug-21	6392	
00191407	982M TURBOCHARGER & WATERPUMP	4-Jul-21	F	80245760	1004	100997	EQ	30-Aug-21	6392	KOOL_2021_27
AM010450	K-JPS BONNET ACTUATOR SYNCHRONISE HARNESS FOR FAILED	25-Jul-21	F	80245760	0021		EQ	30-Aug-21	6392	
00172338	982M ENGINE VALVE SET * 1 X 229-5711 SEAL * #	12-Jun-21	F	80245760	1002	888031	EQ	27-Aug-21	6392	
AM018477	C LAB-51186-2122 HYDRAULICS HIGH WEAR ELEMENTS	20-Jul-21	F	80245760	7000		EQ	27-Aug-21	6392	
AM010761	REPLACE REAR WORKLIGHTS ON CAB NOT WORKING.	15-Jul-21	F	80245760	9000		EQ	26-Aug-21	6392	KOOL_2021_27
AM011504	WHEEL LOADER 12 MONTH AFFF SERVICE	7-Aug-21	F	80245760	IN0707	800033	EQ	19-Jul-21	6391	
AM002464	K-REAR LHS WINDOW CRACKED	12-Jun-21	F	80245760	8000		EQ	7-Jul-21	6390	
AM008031	UNABLE TO CYCLE GREASE MANUALLY. NO SWITCH. CONTACT OEM	29-Jun-21	F	80245760	0091		EQ	5-Jul-21	6390	

Work Order	Description	Start Date	Status	Cost Centre	Comp Code	PM Task	Branch	Finish Date	Done @	Schedule Week
00191408	982M UNIVERSAL JOINT	4-Jul-21	F	80245760	3000	101009	EQ	4-Jul-21	6390	KOOL_2021_27
AM004663	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	4-Jul-21	F	80245760	9000	899995	EQ	4-Jul-21	6390	KOOL_2021_27
AM002465	K-PS-REAR MESH DAMAGED	4-Jul-21	F	80245760	0021		EQ	4-Jul-21	6390	KOOL_2021_27
AM006167	K-PS CHECK ON HEATER OPERATION	4-Jul-21	F	80245760	0021		EQ	4-Jul-21	6390	KOOL_2021_27
AM002466	K-PS-REAR WORKLIGHTS ON CAB NOT WORKING.	4-Jul-21	F	80245760	9000		EQ	4-Jul-21	6390	KOOL_2021_27
AM008001	FRONT PINS DRY MANUAL GREASE AND INSPECT FUNCTION OF GREASE	29-Jun-21	F	80245760	0091		EQ	29-Jun-21	6340	
00189512	K-BD-RIDE CONTROL NOT WORKING	8-Jun-21	F	80245760	0021		EQ	13-Jun-21	6178	KOOL_2021_24
AM003901	24V TO 12V CONVERTER FAILED	11-Jun-21	F	80245760	9000		EQ	11-Jun-21	6174	
00189347	K-BD-REPLACE WORN G.E.T	8-Jun-21	F	80245760	GET		EQ	8-Jun-21	6174	KOOL_2021_24
00188258	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	8-Jun-21	F	80245760	9000	899995	EQ	8-Jun-21	6174	KOOL_2021_24
00192054	-DIAGNOSE AND REPAIR GREASE SYSTEM NOT CYCLING	8-Jun-21	F	80245760	0091		EQ	8-Jun-21	6174	KOOL_2021_24
00188244	CAT 982M LOADER 2000 HR SERVICE	8-Jun-21	F	80245760	P2000	900017	EQ	8-Jun-21	6174	KOOL_2021_24
00192112	INSPECT BUCKET FLOAT OPERATION NEXT AVAILABLE OR NEXT	8-Jun-21	F	80245760	0020		EQ	8-Jun-21	6174	KOOL_2021_24
00188175	K-JPS REPLACE SEAT BELT	8-Jun-21	F	80245760	8995		EQ	8-Jun-21	6174	KOOL_2021_24
00188174	K-JPS REPLACE LEAKING AXLE COOLING HOSE	8-Jun-21	F	80245760	4000-R		EQ	8-Jun-21	6174	KOOL_2021_24
00188172	K-JPS REPLACE SERVICE CENTRE DOOR	8-Jun-21	F	80245760	MISC		EQ	8-Jun-21	6174	KOOL_2021_24
AM000061	X LAB-51140-1615 HYDRAULICS HIGH WEAR ELEMENTS AND WRONG OIL	27-May-21	F	80245760	7000		EQ	31-May-21	6049	
00158178	INSTALL OBJECT DETECTION SYSTEM	9-Feb-21	F	80245760	9000		EQ	15-May-21	5729	
00190308	K-BD-REPLACE WORN G.E.T	18-May-21	F	80245760	GET		EQ	15-May-21	5729	
00178579	CAT 982M LOADER 500 HR SERVICE	10-May-21	F	80245760	P0500	900015	EQ	9-May-21	5688	KOOL_2021_20
00158399	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	10-May-21	F	80245760	9000	899995	EQ	8-May-21	5688	KOOL_2021_20
00177176	REMOVE AND REPLACE SEAT BELT ASSY	8-May-21	F	80245760	8995		EQ	8-May-21	5669	KOOL_2021_19
00188060	BD- RECHARGE FIRE SUPPRESSION	10-May-21	F	80245760	IN0705		EQ	8-May-21	5688	
00175232	CAT 982M LOADER 1000 HR SERVICE	7-Apr-21	F	80245760	P1000	900016	EQ	8-Apr-21	5131	
00177410	GREASE SYSTEM NOT WORKING OR CYCLING	5-Apr-21	F	80245760	0091		EQ	5-Apr-21	5074	
00176388	BD - AIRCON NOT COLD	29-Mar-21	F	80245760	9500		EQ	29-Mar-21	4946	
00173324	BD- AIRCON BLOWING WARM AIR	18-Mar-21	F	80245760	9500		EQ	19-Mar-21	4772	
00161987	CAT 982M LOADER 500 HR SERVICE	26-Apr-21	F	80240760	P0500	900015	EQ	28-Feb-21	4497	
00137034	REPLACE RH BONNET CYL AS IT IS MISSING- JPS COMPLETED	16-Jan-21	F	80245760	8000		EQ	28-Feb-21	4497	KOOL_2021_03
00169023	K-BD REPAIR BROKEN GREASE LINE	24-Feb-21	F	80245760	0001		EQ	25-Feb-21	4451	
00168628	K-BD AIR FILTER RESTRICTION ALARM	23-Feb-21	F	80245760	1000		EQ	23-Feb-21	4442	
00154568	WHEEL LOADER 12 MONTH AFFF SERVICE	29-Jan-21	F	80245760	IN0707	800033	EQ	29-Jan-21	4340	
00142681	A/C REPAIRS	16-Jan-21	F	80245760	9500		EQ	16-Jan-21	4245	KOOL_2021_03
00139523	CAT 982M LOADER 250 HR SERVICE	16-Jan-21	F	80245760	P0250	900014	EQ	16-Jan-21	4245	KOOL_2021_03
00141271	BD - LOAD RITE FAULT - INCORRECT WEIGHTS	12-Nov-20	F	80245760	9000		EQ	12-Dec-20	4244	
00138463	REPLACE POS 3 AND 4 TYRES	7-Nov-20	F	80245760	TYRE		EQ	7-Nov-20	4087	KOOL_2020_45
00115033	PRESTART # HV251073 TEARS IN ALL TYRES	7-Nov-20	F	80249760	INPRE	200000	EQ	7-Nov-20	4087	KOOL_2020_45
00137628	K-CR-P2 Tyre wire exposed	26-Oct-20	F	80245760	9800-2		EQ	26-Oct-20	3976	
00130439	CAT 982M LOADER 2000 HR SERVICE	10-Oct-20	F	80245760	P2000	900017	EQ	25-Oct-20	3975	KOOL_2020_41
00126667	K-JPS- RHR LADDER	10-Oct-20	F	80245760	0001		EQ	25-Oct-20	3975	KOOL_2020_41
00108924	REPLACE AUTOLUBE PUMPING ELEMENT	10-Oct-20	F	80249760	0091		EQ	25-Oct-20	3975	KOOL_2020_41
00126660	K-JPS-C/O RH+LH LIFT CYLINDER RETAINER BOLTS	10-Oct-20	F	80245760	7420-LH		EQ	25-Oct-20	3975	KOOL_2020_41
00123789	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	10-Oct-20	F	80249760	9000	899995	EQ	25-Oct-20	3975	KOOL_2020_41
00132084	K-BD-Bonnet struts not working	30-Sep-20	F	80245760	0001		EQ	30-Sep-20	3871	
00115128	CHANGE POS 3 & 2 TYRE	20-Jul-20	F	80249760	TYRE		EQ	19-Sep-20	3800	
00129032	INVETSIGATE GREASE FAULT & REPAIR	18-Sep-20	F	80245760	0091		EQ	17-Sep-20	3771	
00128303	ZERO LOADRITE SYSTEM	14-Sep-20	F	80245760	9000		EQ	13-Sep-20	3748	
00124438	CALIBRATE TRANS PEDAL- OPERATOR REPORT HARSH DISENGAGEMENT	1-Sep-20	F	80020763	9000		EQ	1-Sep-20	3726	
00123760	CAT 982M LOADER 250 HR SERVICE	31-Aug-20	F	80020763	P0250	900014	EQ	31-Aug-20	3726	35
00124775	MODIFICATION TO 2WAY RADIO	27-Aug-20	F	80245760	9000		EQ	26-Aug-20	3663	
00124057	FULL SYSTEM CALIBRATION	24-Aug-20	F	80020763	9000		EQ	22-Aug-20	3614	
00123917	REPLACE WORN GET BUCKET LIP SHROUDS	23-Aug-20	F	80020763	GET		EQ	22-Aug-20	3614	
00107915	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	14-Aug-20	F	80249760	9000	899995	EQ	17-Aug-20	3544	33
00115224	CAT 982M LOADER 500 HR SERVICE	14-Aug-20	F	80249760	P0500	900015	EQ	14-Aug-20	3513	33
00111894	PRESTART # 251060 Grease Line Disconnected on Boom	25-Jul-20	F	80249760	INPRE	200000	EQ	9-Aug-20	3463	
00111521	PRESTART # 251059 Dashcam Keeps Stopping, No SD card	23-Jul-20	F	80249760	INPRE	200000	EQ	9-Aug-20	3463	
00117111	COMPLETE MOBILISATION AND ON HIRE INSPECTION	21-Jul-20	F	80249760	0001		EQ	29-Jul-20	3340	
00078507	LOADRITE CALIBRATION	16-Jul-20	F	80245760	0001	800016	EQ	16-Jul-20	3297	29
00109546	REPLACE BONNET TILT WORM DRIVE CYLINDERS	14-Jul-20	F	80020763	0001		EQ	13-Jul-20	3287	
00108179	C LAB-20G1500202 POOR COOLANT CONDITION AND CAT ELC USED.	13-Jul-20	F	80020763	1310	400000	EQ	13-Jul-20	3287	29
00111520	PRESTART # 251059 Grease Line Disconnected on boom	23-Jul-20	F	80020763	INPRE	200000	EQ	27-Jun-20	3225	
00110629	CHECK AND REPAIR GREASE LINES	22-Jun-20	F	80020763	7000		EQ	21-Jun-20	3210	
00092559	982M ENGINE VALVE SET	12-Jun-20	F	80245760	1002	888031	EQ	12-Jun-20	3195	24
00104995	PRESTART - AUTO LUB FAULT	6-Jun-20	F	80020763	0091		EQ	12-Jun-20	3193	23
00108176	Resample engine and check intake system	10-Jun-20	F	80020763	1000		EQ	10-Jun-20	3193	
00105190	CAT 982M LOADER 250 HR SERVICE	6-Jun-20	F	80020763	P0250	900014	EQ	10-Jun-20	3193	23
00107753	BUCKET PINS SQUEELING	8-Jun-20	F	80020763	0091		EQ	8-Jun-20	3193	
00104482	X LAB-50G1500629 ENGINE OIL HIGH IRON	29-May-20	F	80020763	1000		EQ	29-May-20	3071	
00105294	CHECK REPORTED SQUEAKY BUCKET PIN	28-May-20	F	80020763	0091		EQ	27-May-20	3060	
00105095	LOADRITE NOT WORKING	23-Jun-20	F	80020763	9000		EQ	25-May-20	3050	
00100954	CAT 982M LOADER 1000 HR SERVICE	19-May-20	F	80020763	P1000	900016	EQ	21-May-20	2987	20
00103461	HOOD LOWERING AND LIFTING INTERMITTANTLY	14-Jun-20	F	80020763	0001		EQ	21-May-20	2987	
00103255	WHEEL LOADER 6 MONTH AFFF SERVICE	12-Jun-20	F	80020763	IN0706	800032	EQ	20-May-20	2986	
00103459	AIR FILTER RESTRICTION WARNING	14-Jun-20	F	80020763	1000		EQ	17-May-20	2957	

Work Order	Description	Start Date	Status	Cost Centre	Comp Code	PM Task	Branch	Finish Date	Done @	Schedule Week
00096492	CAT 982M LOADER 250 HR SERVICE	30-Apr-20	F	80020763	P0250	900014	EQ	30-Apr-20	2801	18
00099619	PRESTART # HV115036	27-May-20	F	80020763	INPRE	200000	EQ	30-Apr-20	2801	
00095142	REPLACE PROXIMITY SENSOR ON GREASE BLOCK	30-Apr-20	F	80020763	0091		EQ	30-Apr-20	2801	18
00093695	PRESTART: REAR LEFT WINDOW CRACKED.	30-Apr-20	F	80020763	0001		EQ	30-Apr-20	2801	18
00093698	PRESTART: RH REAR STEP BENT.	30-Apr-20	F	80020763	0001		EQ	30-Apr-20	2801	18
00093427	Auto grease system fault	26-Mar-20	F	80020763	9000		EQ	20-Apr-20	2663	
00093817	C/O CUTTING EDGES	6-Apr-20	F	80020763	0020		EQ	4-Apr-20	2557	
00092539	CAT 982M LOADER 500 HR SERVICE	31-Mar-20	F	80020763	P0500	900015	EQ	31-Mar-20	2556	13
00070920	MONTHLY PRODUCT STATUS REPORT DOWNLOAD	31-Mar-20	F	80020763	9000	899995	EQ	31-Mar-20	2556	13
00087511	INSTALL TETRA RADIO. RADIO AND FITMENT IN THE CONSUMABLES	31-Mar-20	F	80020763	9000		EQ	31-Mar-20	2556	13
00089846	CAT 982M LOADER 250 HR SERVICE	12-Mar-20	F	80020763	P0250	900014	EQ	13-Mar-20	2430	11
00089487	PRESTART: AUTO LUBE FAULT	12-Mar-20	F	80020763	0091		EQ	13-Mar-20	2430	11
00088291	GREASE LEAK/FAULT.	29-Feb-20	F	80020763	0091		EQ	29-Feb-20		
00086817	WHEEL LOADER 12 MONTH AFFF SERVICE	19-Mar-20	F	80020763	IN0707	800033	EQ	21-Feb-20	2245	
00084598	COMPLETE ON HIRE INSPECTION AND MAMF	11-Feb-20	F	80020763	0001		EQ	18-Feb-20	2245	
00083211	MTM STEMMINGS INSPECTION AND OFFHIRE	4-Feb-20	F	80020763	0001		EQ	8-Feb-20	2243	
00076901	CAT 982M LOADER 2000 HR SERVICE	28-Jan-20	F	80020763	P2000	900017	EQ	29-Jan-20	2164	
00072414	PRESTART # 111759 <SEAT LEAKING AIR>	28-Jan-20	F	80020763	INPRE	200000	EQ	28-Jan-20	2164	
00071894	PRESTART # 111758 <RH SWING STEP BENT>	28-Jan-20	F	80020763	INPRE	200000	EQ	28-Jan-20	2112	
00078639	CHANGE OUT POS 3 TYRE	10-Jan-20	F	80020763	TYRE		EQ	10-Jan-20	1922	
00076979	REPLACE GREASE INJECTORS	2-Jan-20	F	80020763	8000		EQ	2-Jan-20		
00070946	WHEEL LOADER WEEKLY INSPECTION	11-Dec-19	F	80020763	INWK	800012	EQ	11-Dec-19	1680	
00072423	SEAT FAULT	1-Dec-19	F	80020763	8995		EQ	6-Dec-19		
00067286	C LAB - 49G3120401 ENGINE HIGH IRON AND SOOT	19-Nov-19	F	80020763	1000		EQ	26-Nov-19	1572	
00069807	DIAGNOSE & REPAIRS AUTOLUBE FAULT	22-Nov-19	F	80020763	8000		EQ	24-Nov-19	1563	
00068316	COMPLETE ON HIRE INSPECTION AND MAMF	15-Nov-19	F	80020763	0001		EQ	17-Nov-19	1563	
00061328	CAT 982M LOADER 500 HR SERVICE	25-Oct-19	F	80020763	P0500	900015	EQ	27-Oct-19	1561	
00059724	WARRANTY: DIAGNOSE AND REPAIR FAST FILL FUEL FAULT	7-Oct-19	F	80020763	0001		EQ	24-Oct-19	1561	
00060529	WARRANTY: DIAGNOSE AND REPAIR ELECTIRCAL FAULTS	10-Oct-19	F	80020763	0001		EQ	11-Oct-19	1507	
00049766	WHEEL LOADER 6 MONTH AFFF SERVICE - PWR 29/08/19	18-Sep-19	F	80020763	IN0706	800032	EQ	11-Sep-19	1168.7	
00049832	LOADRITE CALIBRATION	21-Aug-19	F	80020763	0001	800016	EQ	22-Aug-19	1163	
00030655	CAT 982M LOADER 1000 HR SERVICE	27-Jul-19	F	80020763	P1000	900016	EQ	6-Aug-19	1130	
00027291	CHANGE OUT POS 1 AND 2 TYRES	26-Jun-19	F	80020763	TYRE		EQ	28-Jun-19	833	
00027204	CAT 982M LOADER 500 HR SERVICE	29-May-19	F	80020763	P0500	900015	EQ	6-Jun-19	660	

Work Order	Description	Start Date	Status	Cost Centre	Comp Code	PM Task	Branch	Finish Date	Done @	Schedule Week
AM041618	982M TURBOCHARGER & WATERPUMP *	10-Oct-22	F	80249760	1004	100997	EQ	13-Oct-22	6706	WODG_2022_40
AM000174	982M SEAT	1-Jul-21	F	80245760	8995	101031	EQ	2-Sep-21	6392	
00191407	982M TURBOCHARGER & WATERPUMP	4-Jul-21	F	80245760	1004	100997	EQ	30-Aug-21	6392	KOOL_2021_27
00191409	982M TRUNNION	2-Jul-21	F	80245760	8430	101030	EQ	30-Aug-21	6392	
00191408	982M UNIVERSAL JOINT	4-Jul-21	F	80245760	3000	101009	EQ	4-Jul-21	6390	KOOL_2021_27