

Work Order	Description	Start Date	Status	Cost Centre	Comp Code	PM Task	Branch	Finish Date	Done @	Schedule Week
00128869	W-JPS-MD6250 AIR COMPRESSOR BELL HOUSING LEAKING. REQUIRES	23-Oct-20	F	80246760	3050	102688	EQ	24-Oct-20	2367	WIND_2020_43
00139164	MD6250 ROTATION MOTOR	1-Dec-20	F	80246760	7000	102679	EQ	4-Nov-20	2547	
00185484	MD6250 HOIST CABLE	13-Sep-21	F	80246760	3000	102676	EQ	10-Sep-21	6433	WIND_2021_38
00185485	MD6250 IMPLIMENT PUMP LH	27-Sep-21	F	80246760	7000	102677	EQ	30-Sep-21	6735	WIND_2021_40
00185486	MD6250 IMPLIMENT PUMP RH	27-Sep-21	F	80246760	7000	102678	EQ	28-Sep-21	6735	WIND_2021_40
00185487	MD6250 ROTATION MOTOR	5-Nov-21	F	80246760	7000	102679	EQ	23-Dec-20	3221	
00185488	MD6250 PISTON PUMP AUXILIARY	27-Sep-21	F	80246760	7000	102681	EQ	30-Sep-21	6735	WIND_2021_40
00185489	MD6250 ROTARY HEAD GEARBOX *	8-Oct-22	F	80246760	3000	102687	EQ	10-Oct-22	9756	WODG_2022_40
00185490	MD6250 PUMP WATER INJECTION	27-Sep-21	F	80246760	7000	102689	EQ	30-Sep-21	6735	WIND_2021_40
00185491	MD6250 SEAT	27-Sep-21	F	80246760	8995	102699	EQ	28-Sep-21	6735	WIND_2021_40
00185492	MD6250 CHARGE PUMP *	9-Oct-22	F	80246760	7000	102714	EQ	10-Oct-22	9756	WODG_2022_40
AM008458	MD6250 ENGINE MIDLIFE	21-Apr-22	F	80246760	1000	102671	EQ	22-Apr-22	8869	WIND_2022_16
AM008459	MD6250 TURBOCHARGER LEFT	21-Apr-22	F	80246760	1000	102672	EQ	21-Apr-22	8869	WIND_2022_16
AM008460	MD6250 TURBOCHARGER RIGHT	21-Apr-22	F	80246760	1000	102673	EQ	21-Apr-22	8869	WIND_2022_16
AM040041	MD6250 SEAT - REPLACE SEAT AGAIN. INCORRECT BASE	17-Oct-21	F	80246760	8995	102699	EQ	17-Oct-21	6966	WIND_2021_42
AM071343	MD6250 HYDRAULIC FAN MOTOR LEFT (ENGINE COOLER)	5-Jun-22	F	80246760	7000	102683	EQ	13-Jun-22	9061	
AM071345	MD6250 HYDRAULIC FAN MOTOR RIGHT (HYDRAULIC COOLER)	13-Jun-22	F	80246760	7000	102684	EQ	16-Jun-22	9062	WIND_2022_24
AM071346	MD6250 HYDRAULIC FAN PUMP LEFT	13-Jun-22	F	80246760	7039	102685	EQ	15-Jun-22	9062	WIND_2022_24
AM071347	MD6250 HYDRAULIC FAN PUMP RIGHT	13-Jun-22	F	80246760	7039	102686	EQ	16-Jun-22	9062	WIND_2022_24
AM071348	MD6250 PUMP DRIVE *	5-Jun-22	F	80246760	3200	102703	EQ	17-Sep-22	9615	
AM073419	MD6250 DECK WRENCH	13-Jun-22	F	80246760	3000	102691	EQ	15-Jun-22	9062	WIND_2022_24
AM080410	BD - C/O MD6250 HOIST & PULL DOWN CABLES	13-Jun-22	F	80246760	3000	102676	EQ	13-Jun-22	9061	WIND_2022_24
AM096408	MD6250 IMPLIMENT PUMP LEFT - PRT.STG	22-Nov-23	F	80700401	7000	102677	EQ	22-Nov-23	12466	MTM_2023_47
AM096421	MD6250 IMPLIMENT PUMP RIGHT - PRT.STG	22-Nov-23	F	80700401	7000	102678	EQ	22-Nov-23	12466	MTM_2023_47
AM096422	MD6250 PISTON PUMP AUXILIARY - PRT.STG	22-Nov-23	F	80700401	7000	102681	EQ	22-Nov-23	12466	MTM_2023_47
AM096423	C/O LEAKING MD6250 PUMP WATER INJECTION	10-Jul-22	F	80246760	7000	102689	EQ	16-Jun-22	9062	
AM096652	MD6250 SEAT - PRT.STG	16-Sep-23	F	80700401	8995	102699	EQ	17-Sep-23	11628	
AM124512	MD6250 COUPLING - ENGINE TO PUMP DRIVE	9-Nov-22	F	80700760	3000	102718	EQ	9-Nov-22	10187	WODG_2022_45
AM283851	MD6250 CYDLINER JACK LEVEL REAR RIGHT -	23-Nov-23	F	80710401	7000	102693	EQ	23-Nov-23	12466	MTM_2023_47
AM283863	MD6250 CYDLINER JACK LEVEL FRONT RIGHT	22-Nov-23	F	80710401	7000	102695	EQ	22-Nov-23	12466	MTM_2023_47
AM283873	MD6250 CYLINDER JACK LEVEL FRONT LEFT	23-Nov-23	F	80710401	7000	102696	EQ	23-Nov-23	12466	MTM_2023_47
AM283891	MD6250 CYDLINER JACK LEVEL REAR LEFT	23-Nov-23	F	80710401	7000	102694	EQ	23-Nov-23	12466	MTM_2023_47
AM324147	MD6250 CYLINDER MAST RAISE LEFT - CYL REQ 614835	4-Aug-24	F	80710401	7000	102697	EQ	22-Jul-24	15637	MTM_2024_31D
AM324148	MD6250 CYLINDER MAST RAISE RIGHT - CYL REQ 614762	23-Nov-23	F	80710401	7000	102698	EQ	23-Nov-23	12466	MTM_2023_47
AM336750	MD6250 FINAL DRIVE LEFT	1-Jan-24	F	80710401	5000-L	102701	EQ	3-Jan-24	13054	MTM_2024_01
AM336751	MD6250 FINAL DRIVE RIGHT	1-Jan-24	F	80710401	5000-R	102702	EQ	3-Jan-24	13054	MTM_2024_01
AM361215	MD6250 ENGINE	1-Jul-26	S	80700401	1000	102670	EQ		0	.
AM361217	MD6250 AIR COMPRESSOR	1-Jul-26	S	80700401	3050	102688	EQ			.
AM393830	X LAB* - REPLACE ROTARY HEAD - REQ 711115	27-Feb-24	F	80710401	8016	102687	EQ	28-Feb-24	14012	MTM_2024_09
AM406371	MD6250 HOIST & PULL DOWN CABLES	5-Mar-24	F	80710401	3000	102676	EQ	6-Mar-24	14019	
AM470300	MD6250 CYLINDER PULL DOWN, LEAKING - REQ 802211	19-Jun-24	F	80710401	7000	102690	EQ	23-Jun-24	15349	
AM499272	MD6250 PUMP WATER INJECTION SEND OLD PUMP TO ROTABLES	1-Jul-26	S	80700401	7000	102689	EQ			.
AM499273	MD6250 COUPLING COMPLETE - ENGINE TO PUMP DRIVE	1-Jul-26	S	80700401	1000	102718	EQ		0	.

Work Order	Description	Start Date	Status	Cost Centre	Comp Code	PM Task	Branch	Finish Date	Done @	Schedule Week
AM499274	MD6250 AIR COMPRESSOR COUPLING COMPLETE	1-Jul-26	S	80700401	1000	102806	EQ		0	.
AM499275	MD6250 ROTATION MOTOR	1-Jul-26	S	80700401	7000	102679	EQ			.
AM499276	MD6250 CHARGE PUMP	1-Jul-26	S	80700401	7000	102714	EQ			.
AM499277	MD6250 COMPRESSOR HOSES	1-Jul-26	S	80700401	3050	102807	EQ			.
AM499278	MD6250 BELT TENSIONER	1-Jul-26	S	80700401	1000	102808	EQ			.
AM499280	MD6250 IMPLIMENT PUMP LEFT, SEND OLD PUMP TO DC	1-Jul-26	S	80700401	7000	102677	EQ			.
AM499281	MD6250 IMPLIMENT PUMP RIGHT, SEND OLD PUMP TO DC	1-Jul-26	S	80700401	7000	102678	EQ			.
AM499283	MD6250 PISTON PUMP AUXILIARY	1-Jul-26	S	80700401	7000	102681	EQ			.
AM499284	MD6250 HYDRAULIC FAN MOTOR LEFT (ENGINE COOLER)	1-Jul-26	S	80700401	7000	102683	EQ			.
AM499285	MD6250 HYDRAULIC FAN MOTOR RIGHT (HYDRAULIC COOLER)	1-Jul-26	S	80700401	7000	102684	EQ			.
AM499286	MD6250 HYDRAULIC FAN PUMP LEFT	1-Jul-26	S	80700401	7039	102685	EQ			.
AM499287	MD6250 HYDRAULIC FAN PUMP RIGHT	1-Jul-26	S	80700401	7039	102686	EQ			.
AM499288	MD6250 PUMP DRIVE	1-Jul-26	S	80700401	3200	102703	EQ			.
AM499289	MD6250 SEAT	1-Jul-26	S	80700401	8995	102699	EQ			.
AM579006	MD6250 ROTARY HEAD GEARBOX - DONE AT WONMUNNA?	1-Jul-26	S	80700401	3000	102687	EQ			.