

LOT #	BUILDING	MAKE	SERIAL NUMBER	FLOOR	BATHROOM	TOILET	A/C	SECURITY DOOR	ENSEMBLE	MATTRESS	FRIDGE	TV	DESK	CHAIR	VANITY	CONDITION	COMMENTS		
L BLOCK																			
	L1	BLUE RIDGE - PORTABLE/ LIFESTYLE LIVING	BR7 906437		√	√	√	√	√	√	√	√	√	√	x1	√	Good	Note blocks L,M,N are not Ausco-Blue ridge	
	L2			√	√	√	√	√	√	√	√	√	√	√	√	x2	√	Fair	Minor paint flaking, lino cracked
	L3			√	√	√	√	√	√	√	√	√	√	√	√	x1	√	Fair	Minor paint flaking
	L4			√	√	√	√	√	√	√	√	√	√	√	√	x1	√	Good	Mod paint flaking
	L5	BLUE RIDGE - PORTABLE/ LIFESTYLE LIVING	BR7 906438		√	√	√	√	√	√	√	√	x	√	x2	√	Fair	Minor paint flaking, some minor mould spotting	
	L6			√	√	√	√	√	√	√	√	√	√	√	x2	√	Fair	Mod paint flaking	
	L7			√	√	√	√	√	√	√	√	√	x	√	x2	√	Fair	Minor paint flaking	
	L8			√	√	√	√	√	√	√	√	√	x	√	x1	√	Fair	Mod paint flaking	
	L9	BLUE RIDGE - PORTABLE/ LIFESTYLE LIVING	BR7 906439		√	√	√	√	√	√	√	√	x	√	x1	√	Fair	Minor paint flaking	
	L10			√	√	√	√	√	√	√	√	√	√	√	x2	√	Fair	Minor paint flaking	
	L11			√	√	√	√	√	√	√	√	√	√	√	x2	√	Fair	Minor paint flaking, wall rot TV wall	

LOT #	BUILDING	MAKE	SERIAL NUMBER	FLOOR	BATHROOM	TOILET	A/C	SECURITY DOOR	ENSEMBLE	MATTRESS	FRIDGE	TV	DESK	CHAIR	VANITY	CONDITION	COMMENTS	
	L12	LIVING			✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Poor	Moderate paint flaking some mould colouration	
	L13	BLUE RIDGE - PORTABLE/ LIFESTYLE LIVING	BR7 906434		✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Minor Paint flaking, Vynal cracking, water damage bottom of cupboard	
	L14			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Good		
	L15			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x1	✓	Fair	Minor Paint flaking, water damage bottom of cupboard
	L16			✓	✓	✓	✓	✓	✓	✓	✓	✓	×	✓	x1	✓	Fair	Minor paint flaking, Vinyl cracking
	L17					✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x1	✓	Fair

LOT #	BUILDING	MAKE	SERIAL NUMBER	FLOOR	BATHROOM	TOILET	A/C	SECURITY DOOR	ENSEMBLE	MATTRESS	FRIDGE	TV	DESK	CHAIR	VANITY	CONDITION	COMMENTS	
	L18	BLUE RIDGE - PORTABLE/ LIFESTYLE LIVING	BR7 906436		√	√	√	√	√	√	√	√	√	x2	√	Fair	Minor paint flaking, water damage bottom of cupboard, Door hinges rusted- no veranda 16-20	
	L19				√	√	√	√	√	√	√	√	√	√	x2	√	Fair	Minor paint flaking, water damage bottom of cupboard, Door hinges rusted- no veranda 16-20
	L20				√	√	√	√	√	√	√	√	√	√	x2	√	Fair	Water damage bottom of cupboard, Door hinges rusted- No veranda 16-20
	L21				√	√	√	√	√	√	√	√	√	√	x2	√	Fair	Bottom of cupboard water damaged

LOT #	BUILDING	MAKE	SERIAL NUMBER	FLOOR	BATHROOM	TOILET	A/C	SECURITY DOOR	ENSEMBLE	MATTRESS	FRIDGE	TV	DESK	CHAIR	VANITY	CONDITION	COMMENTS	
	L22	BLUE RIDGE - PORTABLE/LIFESTYLE LIVING	BR7 906432		√	√	√	√	√	√	√	√	√	x2	√	Fair	Bottom of cupboard water damaged, minor paint flaking	
	L23			√	√	√	√	√	√	√	√	√	√	√	x2	√	Good	No external handle
	L24			√	√	√	√	√	√	√	√	√	√	√	x2	√	Fair	Minor paint flaking, bottom of cupboard water damaged.
	L25	BLUE RIDGE - PORTABLE/LIFESTYLE LIVING	BR7 906441		√	√	√	√	√	√	√	√	x	x2	√	Fair	Minor paint flaking	
	L26			√	√	√	√	√	√	√	√	√	x	x2	√	Good		
	L27			√	√	√	√	√	√	√	√	√	x	x2	√	Fair	Internal handle damaged	
	L28			√	√	√	√	√	√	√	√	√	x	x2	√	Fair	Minor paint flaking, minor water damage behind fridge	
L29				√	√	√	√	√	√	√	√	x	x2	√	Fair	Moderate paint flaking, bottom of cupboard water damaged, vinyl cracking		

LOT #	BUILDING	MAKE	SERIAL NUMBER	FLOOR	BATHROOM	TOILET	A/C	SECURITY DOOR	ENSEMBLE	MATTRESS	FRIDGE	TV	DESK	CHAIR	VANITY	CONDITION	COMMENTS	
	L30	BLUE RIDGE - PORTABLE/ LIFESTYLE LIVING	BR7 906442		√	√	√	√	√	√	√	×	√	x2	√	Fair	Bottom of cupboard water damaged	
	L31			√	√	√	√	√	√	√	√	√	√	√	x2	√	Fair	Bottom of cupboard water damaged, lino cracked, bed light fallen
	L32			√	√	√	√	√	√	√	√	√	×	√	x2	√	Fair	Minor paint flaking, bottom of cupboard water damaged, Vinyl cracking
	L33	BLUE RIDGE - PORTABLE/ LIFESTYLE LIVING	BR7 906431		√	√	√	√	√	√	√	×	√	x2	√	Fair	Moderate paint flaking, bottom of cupboard water damaged, lino cracked, main room ceiling water stains	
L34	√			√	√	√	√	√	√	√	√	√	√	x2	√	Fair	Large vinyl cracking	

LOT #	BUILDING	MAKE	SERIAL NUMBER	FLOOR	BATHROOM	TOILET	A/C	SECURITY DOOR	ENSEMBLE	MATTRESS	FRIDGE	TV	DESK	CHAIR	VANITY	CONDITION	COMMENTS	
	L35	BLUE RIDGE - PORTABLE/ LIFESTYLE LIVING	BR7 906433		√	√	√	√	√	√	√	√	√	x2	√	Fair	Minor paint flaking Large vinyl cracking	
	L36				√	√	√	√	√	√	√	√	√	√	x2	√	poor	Moderate paint flaking, Large vinyl cracking
	L37				√	√	√	√	√	√	√	√	√	√	x2	√	Fair	Minor paint flaking, vinyl cracking
	L38				√	√	√	√	√	√	√	√	√	√	x2	√	Fair	Minor paint flaking, bottom of cupboard water damaged, lino cracked
	L39				√	√	√	√	√	√	√	√	√	√	x2	√	Fair	Minor paint flaking, bottom of cupboard water damaged, vinyl cracking
	L40				√	√	√	√	√	√	√	√	√	√	x2	√	Fair	Bottom of cupboard water damaged

LOT #	BUILDING	MAKE	SERIAL NUMBER	FLOOR	BATHROOM	TOILET	A/C	SECURITY DOOR	ENSEMBLE	MATTRESS	FRIDGE	TV	DESK	CHAIR	VANITY	CONDITION	COMMENTS	
	L41	BLUE RIDGE - PORTABLE/LIFESTYLE LIVING	BR7 906429		✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Minor paint flaking above entry door	
	L42			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x1	✓	Fair	Minor paint flaking behind fridge
	L43			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Good	
	L44			✓	✓	✓	✓	✓	✓	✓	✓	✓	×	✓	x2	✓	Fair	Minor paint flaking, bottom of cupboard water damaged
	L45	BLUE RIDGE - PORTABLE/LIFESTYLE LIVING	BR7 906435		✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Bottom of cupboard water damaged	
	L46			✓	✓	✓	✓	✓	✓	✓	✓	×	✓	x2	✓	Fair	Bottom of cupboard water damaged, Vynal cracking	
	L47			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Good		
	L48			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Good	Cupboard water damaged	
	L49	BLUE RIDGE - PORTABLE/LIFESTYLE LIVING	BR7 906430		✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Bottom of cupboard water damaged, Vinyl cracking	
	L50			✓	✓	✓	✓	✓	✓	✓	✓	×	✓	x2	✓	Good		
	L51			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Minor paint flaking	

LOT #	BUILDING	MAKE	SERIAL NUMBER	FLOOR	BATHROOM	TOILET	A/C	SECURITY DOOR	ENSEMBLE	MATTRESS	FRIDGE	TV	DESK	CHAIR	VANITY	CONDITION	COMMENTS	
	L52	LIFESTYLE LIVING			✓	✓	✓	✓	✓	✓	✓	×	✓	x3	✓	Fair	Minor paint flaking, Bottom of cupboard water damaged, Vinyl cracking, No TV	
	L53	BLUE RIDGE - PORTABLE/ LIFESTYLE LIVING	BR7 906440		✓	✓	✓	✓	✓	✓	×	×	✓	x2	✓	Fair	Walls Tape marked, No fridge, No TV	
	L54				✓	✓	✓	✓	✓	✓	✓	×	×	✓	x2	✓	Good	No fridge, No TV
	L55				✓	✓	✓	✓	✓	×	✓	×	×	✓	x2	✓	Fair	Vinyl cracking, Mattress only, No TV, No fridge
	L56				✓	✓	✓	✓	✓	×	✓	×	✓	✓	x2	✓	Fair	Bottom of cupboard water damaged, room has been open to the elements and is full of sand No fridge, mattress
	L Laundry																	Fair
		BLUE RIDGE - PORTABLE/ LIFESTYLE LIVING	BR7 906443															

M BLOCK

LOT #	BUILDING	MAKE	SERIAL NUMBER	FLOOR	BATHROOM	TOILET	A/C	SECURITY DOOR	ENSEMBLE	MATTRESS	FRIDGE	TV	DESK	CHAIR	VANITY	CONDITION	COMMENTS	
	M1	BLUE RIDGE	BR7 906427		√	√	√	√	√	×	√	√	√	x2	√	Fair	Bottom of cupboard water damaged, Vinyl cracking, Mattress base only	
	M2				√	√	√	√	√	√	√	√	√	√	x2	√	Fair	Minor paint flaking, Minor vinyl cracking
	M3				√	√	√	√	√	√	√	√	√	√	x2	√	Fair	Minor paint flaking, bottom of cupboard water damaged, minor vinyl cracking
	M4				√	√	√	√	√	√	√	√	√	√	x2	√	Fair	Minor paint flaking, bottom of cupboard water damaged, vinyl cracking
	M5				√	√	√	√	√	√	√	√	√	√	x3	√	Fair	Bottom of cupboard water cracking, vinyl cracking

LOT #	BUILDING	MAKE	SERIAL NUMBER	FLOOR	BATHROOM	TOILET	A/C	SECURITY DOOR	ENSEMBLE	MATTRESS	FRIDGE	TV	DESK	CHAIR	VANITY	CONDITION	COMMENTS	
	M19	BLUE RIDGE	BR7 906422	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x1	✓	Fair	Bottom of cupboard water damaged, lino cracked, minor paint flaking	
	M20			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Minor paint flaking, bottom of cupboard water damaged, vinyl cracking
	M21	BLUE RIDGE	BR7 906425	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x1	✓	Fair	Minor paint flaking, vinyl cracking	
	M22			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Vinyl cracking
	M23			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x1	✓	Fair	Vinyl cracking
	M24	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x1	✓	Fair	Vinyl cracking	
	M25	BLUE RIDGE	BR7 906424	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x1	✓	Fair	Bottom of cupboard water damaged, vinyl cracking	
	M26			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x1	✓	Fair	Minor paint flaking, vinyl cracking
	M27			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Vinyl cracking

LOT #	BUILDING	MAKE	SERIAL NUMBER	FLOOR	BATHROOM	TOILET	A/C	SECURITY DOOR	ENSEMBLE	MATTRESS	FRIDGE	TV	DESK	CHAIR	VANITY	CONDITION	COMMENTS
	M28				√	√	√	√	√	√	√	√	√	x2	√	Fair	Minor paint flaking, lots of rodent excrement
	M29				√	√	√	√	√	√	√	√	√	x2	√	Fair	Bottom of cupboard water damaged, vinyl cracking
	M30				√	√	√	√	√	√	√	√	√	x2	√	Good	
	M31	BLUE RIDGE	BR7 906417		√	√	√	√	√	√	√	√	√	x2	√	Poor	Moderate paint flaking, large vinyl cracking, bottom of cupboard water damaged
	M32				√	√	√	√	√	√	√	√	√	x2	√	Fair	Bottom of cupboard water damaged
	M33				√	√	√	√	√	√	√	√	√	x1	√	Fair	Minor paint flaking, vinyl cracking
	M34				√	√	√	√	√	√	√	√	√	x2	√	Fair	Vinyl cracking
	M35	BLUE RIDGE	BR7 906415		√	√	√	√	√	√	√	√	√	x3	√	Fair	Bottom of cupboard water damaged, Vinyl cracking

LOT #	BUILDING	MAKE	SERIAL NUMBER	FLOOR	BATHROOM	TOILET	A/C	SECURITY DOOR	ENSEMBLE	MATTRESS	FRIDGE	TV	DESK	CHAIR	VANITY	CONDITION	COMMENTS		
	M36				√	√	√	√	√	√	√	√	√	x1	√	Fair	Minor paint flaking, Vinyl cracking		
	M37	BLUE RIDGE	BR7 906419		√	√	√	√	√	×	×	√	√	√	x1	√	Fair	Bottom of cupboard water damaged, No bed	
	M38				√	√	√	√	√	√	√	√	√	√	√	x1	√	Fair	Minor paint flaking
	M39				√	√	√	√	√	√	√	√	√	√	√	x2	√	Fair	Minor paint flaking, vynal cracking
	M40				√	√	√	√	√	√	√	√	√	√	√	x1	√	Fair	Minor paint flaking, vynal cracking
	M41				√	√	√	√	√	√	√	√	√	√	√	x5	√	Fair	Bottom of cupboard water damaged, vinyl cracking, No veranda 41-44
	M42				√	√	√	√	√	√	√	√	√	√	√	x2	√	Fair	Vinyl cracking

LOT #	BUILDING	MAKE	SERIAL NUMBER	FLOOR	BATHROOM	TOILET	A/C	SECURITY DOOR	ENSEMBLE	MATTRESS	FRIDGE	TV	DESK	CHAIR	VANITY	CONDITION	COMMENTS
	M43	BLUE RIDGE	BR7 906411		✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Poor	Minor paint flaking, heavy water damaged behind WC, bottom of cupboard water damaged, vinyl cracking
	M44			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x5	✓	Fair
	M45	BLUE RIDGE	BR7 906416		✓	✓	✓	✓	✓	✓	✓	✓	✓	x3	✓	Fair	Vinyl cracking, caution ants colony at the door
	M46			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Vinyl cracking
	M47			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Minor paint flaking, lino cracking
	M48			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Good	
	M49			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Vinyl cracking
	M50	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Bottom of cupboard water damaged		

LOT #	BUILDING	MAKE	SERIAL NUMBER	FLOOR	BATHROOM	TOILET	A/C	SECURITY DOOR	ENSEMBLE	MATTRESS	FRIDGE	TV	DESK	CHAIR	VANITY	CONDITION	COMMENTS
	M51	BLUE RIDGE	BR7 906410		✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Minor paint flaking, large vinyl cracking, bottom of cupboard water damaged
	M52			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Good
	M53	BLUE RIDGE	BR7 906423		✓	✓	✓	✓	✓	✓	✓	✓	✓	x1	✓	Fair	Bottom of cupboard water damaged
	M54			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2		Good	
	M55			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2		Good	
	M56			✓	✓	✓	✓	✓	✓	×	✓	✓	✓	x2		Fair	Minor paint flaking, desk water damaged
	M laundry	BLUE RIDGE	BR7 906444													Poor	Store/Chemical Store, S/S Trough, Cabinet, Ironing Board
N BLOCK																	
	N1	BLUE RIDGE	BR7 906407		✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Strong odours unsure what from
	N2			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Vinyl cracking
	N3			✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Vinyl cracking

LOT #	BUILDING	MAKE	SERIAL NUMBER	FLOOR	BATHROOM	TOILET	A/C	SECURITY DOOR	ENSEMBLE	MATTRESS	FRIDGE	TV	DESK	CHAIR	VANITY	CONDITION	COMMENTS
	N4				✓	✓	✓	✓	✓	✓	✓	✓	✓	x3	✓	Fair	Strong odours unsure what from
	N5				✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Vinyl cracking
	N6				✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Large vinyl cracking
	N7	BLUE RIDGE	BR7 906413		✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Large vinyl cracking
	N8				✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Minor paint flaking, Large vinyl cracking
	N9				✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Vinyl cracking
	N10				✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Vinyl cracking
	N11	BLUE RIDGE	BR7 906412		✓	✓	✓	✓	✓	✓	✓	✓	✓	x1	✓	Fair	Vinyl cracking, bottom of cupboard water damaged
	N12				✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Vinyl cracking, desk + cupboard water damaged
	N13				✓	✓	✓	✓	✓	✓	✓	✓	✓	x3	✓	Fair	Vinyl cracking, bottom of cupboard water damaged
	N14	BLUE RIDGE	BR7 906403		✓	✓	✓	✓	✓	✓	✓	✓	✓	x1	✓	Fair	Minor paint flaking

LOT #	BUILDING	MAKE	SERIAL NUMBER	FLOOR	BATHROOM	TOILET	A/C	SECURITY DOOR	ENSEMBLE	MATTRESS	FRIDGE	TV	DESK	CHAIR	VANITY	CONDITION	COMMENTS		
	N15				√	√	√	√	√	√	√	√	√	x2	√	Fair	Minor paint flaking		
	N16				√	√	√	√	√	√	√	√	√	√	√	x1	√	Fair	Minor paint flaking, vinyl cracking
	N17				√	√	√	√	√	√	√	√	√	√	√	x2	√	Fair	Minor paint flaking, vinyl cracking, desk base water damaged
	N18	BLUE RIDGE	BR7 906409		√	√	√	√	√	√	√	√	√	x2	√	Fair	Large vinyl cracking		
	N19				√	√	√	√	√	√	√	√	√	x2	√	Fair	Large vinyl cracking		
	N20				√	√	√	√	√	√	√	√	√	x2	√	Fair	Large vinyl cracking		
	N21				√	√	√	√	√	√	√	√	√	x1	√	Fair	Minor paint flaking, large vinyl cracking		
	N22				√	√	√	√	√	√	√	√	√	√	x2	√	Fair	Large vinyl cracking	
	N23				BLUE RIDGE	BR7 906414	√	√	√	√	√	√	√	√	√	x1	√	Fair	Large vinyl cracking

LOT #	BUILDING	MAKE	SERIAL NUMBER	FLOOR	BATHROOM	TOILET	A/C	SECURITY DOOR	ENSEMBLE	MATTRESS	FRIDGE	TV	DESK	CHAIR	VANITY	CONDITION	COMMENTS
	N24				✓	✓	✓	✓	✓	✓	✓	✓	✓	x1	✓	Fair	Minor paint flaking, vinyl cracking, bottom of cupboard water damaged
	N25				✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Vinyl cracking
	N26				✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Minor paint flaking, large vinyl cracking
	N27	BLUE RIDGE	BR7 906420		✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Minor paint flaking, vinyl cracking
	N28				✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Minor paint flaking, vinyl cracking, bottom of cupboard water damaged
	N29				✓	✓	✓	✓	✓	✓	✓	✓	✓	x3	✓	Fair	internal wall warped end of building, rest ok
	N30	BLUE RIDGE	BR7 906426		✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Minor paint cracking, lino cracked

LOT #	BUILDING	MAKE	SERIAL NUMBER	FLOOR	BATHROOM	TOILET	A/C	SECURITY DOOR	ENSEMBLE	MATTRESS	FRIDGE	TV	DESK	CHAIR	VANITY	CONDITION	COMMENTS	
	N31				✓	✓	✓	✓	✓	×	×	✓	×	✓	x2	✓	Good	31-32 couples room internal wall removed, no mattress
	N32				✓	✓	✓	✓	✓	×	×	✓	×	✓	x2	✓	Good	
	N33				✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Minor paint flaking bottom of cupboard water damaged, vinyl cracking
		BLUE RIDGE	BR7 906404															
	N34				✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	minor paint flaking, vinyl cracking
	N35				✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Good	
	N36				✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Vinyl cracking
	N37				✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x1	✓	Good	
	N38				✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x1	✓	Fair	Minor paint flaking
	N39				✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x1	✓	Fair	Minor paint flaking
N40																	Poor	Moderate paint cracking, desk water damaged, toilet ceiling water stained
		BLUE RIDGE	BR7 906402		✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓			

LOT #	BUILDING	MAKE	SERIAL NUMBER	FLOOR	BATHROOM	TOILET	A/C	SECURITY DOOR	ENSEMBLE	MATTRESS	FRIDGE	TV	DESK	CHAIR	VANITY	CONDITION	COMMENTS	
	N41	BLUE RIDGE	BR7 906401		✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Bottom of cupboard water damaged	
	N42				✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x3	✓	Good	
	N43				✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Minor paint flaking previously repaired
	N44				✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x3	✓	Fair	minor paint flaking, bottom of cupboard water damaged
	N45	BLUE RIDGE	BR7 906405		✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Vinyl cracking	
	N46				✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Vinyl cracking
	N47				✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x3	✓	Fair	Vinyl cracking
	N48				✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x4	✓	Fair	Minor paint flaking
	N49	BLUE RIDGE	BR7 906408		✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Fair	Minor paint flaking	
	N50				✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x2	✓	Good	
	N51				✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x1	✓	Fair	Vinyl cracking
	N52				✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	x1	✓	Fair	Minor paint flaking
	N53					✓	✓	✓	✓	✓	✓	✓	✓	x1	✓	Poor	Moderate paint flaking, some mould, lino cracking	

LOT #	BUILDING	MAKE	SERIAL NUMBER	FLOOR	BATHROOM	TOILET	A/C	SECURITY DOOR	ENSEMBLE	MATTRESS	FRIDGE	TV	DESK	CHAIR	VANITY	CONDITION	COMMENTS	
	N54	BLUE RIDGE	BR7 906406		√	√	√	√	√	√	√	√	√	x5	√	Fair	Minor paint flaking, vinyl cracking	
	N55				√	√	√	√	√	√	√	√	√	√	x2	√	Fair	Minor paint flaking, vinyl cracking
	N56				√	√	√	√	√	√	√	√	√	√	x2	√	Fair	Minor paint flaking, vinyl cracking