

DZ8201 DE-MOBE PICTURES



Machine Asset ID



LH Rear View



LH Side View

Oil leaking from both Blade Lift Cyl and Blade Trunnion Mount



Front View showing 2 x Lift Cyl Leaking



RH Front View



RH View



Rear View



Top Engine cover with Exhaust stacks removed



Internal Cab (Parts have been removed)



Cab Floor Plate removed?





Front Blade View



Rear Blade View



Parts Crate